

# STEERING RACK BOOT

## NISSAN Replace parts

|                                                                                    |                                                             |
|------------------------------------------------------------------------------------|-------------------------------------------------------------|
|    | LHC0325<br>48203-01F00<br>B11, B12<br>STEERING BOOT         |
|    | LHC3453<br>48204-01F00<br>B12<br>STEERING BOOT              |
|    | LHC0395<br>48204-W1000<br>180B<br>STEERING BOOT             |
|    | LHC0402<br>48203-W1000<br>180B<br>STEERING BOOT             |
|    | LHC0330<br>48203-D0301<br>B11<br>P/STEERING BOOT            |
|    | LHC0331<br>48204-D0301<br>B11<br>P/STEERING BOOT            |
|  | LHCR3038<br>48204-05F00<br>NISSAN<br>STEERING BOOT          |
|  | LHC3426<br>48203-05F00<br>SENTRA, BLUEBIRD<br>STEERING BOOT |
|  | LHCR3039<br>48204-42L25<br>NISSAN<br>STEERING BOOT          |
|  | LHC3453<br>48204-53A00<br>SENTRA<br>STEERING BOOT           |

## TOYOTA Replace parts

|                                                                                     |                                                                          |
|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|
|    | LHC2541<br>45535-12011<br>TOYOTA<br>STEERING BOOT                        |
|    | LHC2542<br>45536-12011<br>TOYOTA<br>STEERING BOOT                        |
|    | LHC2543<br>45536-12030<br>TOYOTA<br>STEERING BOOT                        |
|    | LHC3334<br>45535-16020<br>TOYOTA<br>STEERING BOOT                        |
|    | LHC3343<br>45535-12030<br>TOYOTA<br>STEERING BOOT                        |
|    | LHC3882<br>47.5x69.5x154<br>45535-22060<br>CRESSIDA '89<br>STEERING BOOT |
|  | LHC3911<br>45535-22040<br>ACER, MARK II<br>STEERING BOOT                 |
|  | LHC3910<br>45535-22030<br>HIACE<br>STEERING BOOT                         |
|  | LHC2547<br>45535-87701<br>DAIHATSU G10<br>STEERING BOOT                  |
|  | LHC2548<br>45535-87702<br>DAIHATSU G11<br>STEERING BOOT                  |

## MAZDA, HONDA Replace parts

|                                                                                      |                                                          |
|--------------------------------------------------------------------------------------|----------------------------------------------------------|
|    | LHC3451<br>B001-32-118<br>323<br>STEERING BOOT, LH       |
|    | LHC3452<br>B001-32-125<br>323<br>STEERING BPPT, RH       |
|    | LHC0112<br>BA29-32-118<br>MAZDA 323<br>STEERING BOOT     |
|    | LHC2674<br>B093-32-125<br>323<br>P/ STEERING BOOT        |
|    | LHC0069<br>H002-32-125<br>626<br>STEERING BOOT           |
|    | LHC3636<br>GJ22-32-125<br>MAZDA 626 '88<br>STEERING BOOT |
|  | LHC0190<br>S231-32-125<br>BONGO<br>STEERING BOOT         |
|  | LHCR3036<br>53537-SA5-000<br>HONDA<br>STEERING BOOT      |
|  | LHC2546<br>53534-SA5-950<br>HONDA<br>STEERING BOOT       |
|  | LHC2554<br>53534-634-020<br>HONDA<br>STEERING BOOT       |

# ENGINE & GEAR BOX MOUNTING

**SUZUKI**

Replace parts



LHC0716  
11710-80000  
SUZUKI SJ410  
ENG. MOUNT, R



LHC3633  
11610-80000  
SUZUKI SJ410  
ENG. MOUNT, F



LHC3299  
11710-80010  
SJ410 83-90  
ENGINE MOUNT, R



LHC3663  
11610-86300  
SUZUKI SA310  
ENG. MOUNT, F



LHC3664  
11610-82210  
SUZUKI SA310  
ENG. MOUNT, F




LHC4051  
11710-86300  
SA310  
ENGINE MOUNT, R



LHC4218  
11610-60A01  
VITARA 89-90  
ENGINE MOUNT, F



LHC4348  
11910-60A02  
VITARA 91-94  
ENGINE MOUNT BUSH



LHC4444  
11620-58B00  
VITARA 91-93  
ENGINE MOUNT, F




LHC4297  
11710-60A01  
VITARA 91-93  
ENG. MOUNT, R

**SUZUKI**

Replace parts



LHC3970  
11910-82601  
SUZUKI SA310  
BUFFER



LHC3969  
11810-82601  
FORSA 85'  
SA310 BUFFER



LHC4140  
11620-82020  
SJ413, SA310 84-87  
ENGINE MOUNT, R



LHC4095  
11610-60B10  
FORSA II '90  
ENGINE MOUNT



LHC4405  
11710-60B50  
SWIFT 90-94 ATM  
ENGINE MOUNT, R



LHC4396  
11910-60B20  
FORSA II '90  
BUFFER



LHC4395-11  
11620-71C10  
SWIFT 90-94  
ENGINE MOUNT, LH



LHC4436  
11610-71C10  
SWIFT 92-93 MTM  
ENGINE MOUNT, RH



LHC4394  
11710-63B10  
SWIFT 90-94 MTM  
ENGINE MOUNT, R



LHC0725  
11620-77100  
SUZUKI ST90, SK410  
ENGINE MOUNT, F

**DAIHATSU**

Replace parts



LHC0886  
12361-87703/4  
CHARADE G11  
ENGINE MOUNT, F



LHC0888  
12373-87702/3  
CHARADE G11  
ENGINE MOUNT, R



LHC4498  
12305-87706  
DAIHATSU G102  
ENGINE MOUNT, RH



LHC4359  
12305-87701  
G100 1.0 88-92  
ENGINE MOUNT



LHC4370  
12307-87706  
G100 88-92 MT  
ENGINE MOUNT



LHC4499  
12371-87713  
DAIHATSU G130  
ENGINE MOUNT, R



LHC4372  
12303-87703  
G100 1.0 88-92  
ENGINE MOUNT, R



LHC0771  
12361-87383  
DYNA, V22  
ENGINE MOUNT, F



LHC0772  
12371-87305  
DYNA, V22  
ENGINE MOUNT, R



LHC4023  
12371-87308  
V54  
ENGINE MOUNT, R

# ENGINE & GEAR BOX MOUNTING

|                                                                                                                                                         |                                                                                                                                                           |                                                                                                                                                                              |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC1601<br/>1807.25<br/>PEUGEOT 504<br/>ENG. MOUNT, F</p>           |  <p>LHC0831<br/>7704001320<br/>RENAULT R9<br/>ENGINE MOUNT, F</p>        |  <p>LHC1671<br/>1221915<br/>VOLVO<br/>ENGINE MOUNT, F</p>                                  |
|  <p>LHC3272<br/>1843.62<br/>PEUGEOT 504<br/>GEAR BOX MOUNT</p>          |  <p>LHC0832<br/>7704001319<br/>RENAULT R9<br/>ENG. MOUNT, F</p>          |  <p>LHC1672<br/>1206216<br/>VOLVO<br/>ENGINE MOUNT, R</p>                                  |
|  <p>LHC1914<br/>1843.73<br/>PEUGEOT 305<br/>ENGINE MOUNT</p>            |  <p>LHC0822<br/>7704001317<br/>RENAULT R9<br/>ENG. MOUNT, R</p>          |  <p>LHC4298<br/>191-199-279C<br/>JETTA, GOLF 92-96<br/>ENGINE MOUNT</p>                    |
|  <p>LHC3112<br/>1844.17<br/>PEUGEOT 305<br/>MOUNTING SUPPORT</p>        |  <p>LHC3488<br/>7700759489<br/>R25<br/>ENGINE MOUNT, F</p>               |  <p>LHC3036<br/>23278-4<br/>SEAT 1.5, FIATess<br/>ENG. MOUNT, RH</p>                       |
|  <p>LHC3133<br/>1843.50<br/>305<br/>ENGINE MOUNT, R</p>                 |  <p>LHC1651<br/>BMW 318<br/>ENG. MOUNT, RH</p>                           |  <p>LHC1938<br/>11B5671<br/>ROVER<br/>ENG. MOUNT, F RH</p>                                 |
|  <p>LHC3034<br/>1843.57<br/>305<br/>ENGINE MOUNT, R</p>                 |  <p>LHC1652<br/>BMW 318<br/>ENG. MOUNT, LH</p>                           |  <p>LHC1942<br/>12x73x27<br/>JHM269<br/>ROVER<br/>ENGINE MOUNT, R</p>                      |
|  <p>LHC3613<br/>1843.82<br/>PEUGEOT 205<br/>ENGINE MOUNT, LH</p>      |  <p>LHC1653<br/>BMW 318<br/>ENG. MOUNT, R</p>                          |  <p>LHC2033<br/>JHM801<br/>ROVER<br/>ENGINE MOUNT</p>                                     |
|  <p>LHC0023<br/>711F-6068-AB<br/>FORD CORTINA<br/>ENGINE MOUNT, R</p> |  <p>LHC2123<br/>123 241 3013<br/>MERCEDES BENZ<br/>ENGINE MOUNT, F</p> |  <p>LHC3754<br/>TEM1155<br/>2823491<br/>HOLDEN, COMMODORE<br/>ENGINE MOUNT</p>           |
|  <p>LHC2190<br/>85HF-6038-EA<br/>FORD SIERRA<br/>ENGINE MOUNT, F</p>  |  <p>LHC2124<br/>116 241 0813<br/>BENZ<br/>ENG. MOUNT, F</p>            |  <p>LHC3093<br/>TEM1155<br/>7432236<br/>HOLDEN, COMMODORE<br/>ENGINE MOUNT, R</p>        |
|  <p>LHC4145<br/>91DA-6068-AA<br/>FORD<br/>ENGINE MOUNT</p>            |  <p>LHC1661<br/>116 240 0418<br/>BENZ<br/>ENG. MOUNT, R</p>            |  <p>LHC1701<br/>XW6068C<br/>COMMODORE, FALCON<br/>ZEPHYR, HOLDEN<br/>ENGINE MOUNT, R</p> |

# SUSPENSION BUSH

**NISSAN** Replace parts

|                                                                                                                                                  |                                                                                                                                                        |                                                                                                                                                           |
|--------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC0302</b><br>54504-01A00<br>B11<br>SUSPENSION BUSH      | <br><b>LHC3483</b><br>54476-01B00<br>NISSAN MARCH<br>SUSPENSION BUSH  | <br><b>LHC3434</b><br>54590-Q9000<br>54590-01E00<br>BLUEBIRD<br>ARM BUSH |
| <br><b>LHC0303</b><br>54505-01A00<br>B11<br>SUSPENSION BUSH      | <br><b>LHC4464</b><br>54560-17B01<br>MARCH<br>ARM BUSH                | <br><b>LHC3332</b><br>54596-01E00<br>BLUEBIRD<br>ARM BUSH                |
| <br><b>LHC0304</b><br>55045-01A05<br>SENTRA B11<br>SUSP. BUSH, R | <br><b>LHC4205</b><br>54476-41B02<br>MARCH '92<br>ARM BUSH            | <br><b>LHC0476</b><br>BLUEBIRD, SKYLINE<br>BUSH, LINK                    |
| <br><b>LHC0339</b><br>54560-50A00<br>SENTRA E16<br>SUSP. BUSH    | <br><b>LHC4545</b><br>54570-50J00<br>PRIMERA 91-97<br>ARM BUSH        | <br><b>LHC0477</b><br>55045-Q0103<br>BLUEBIRD, SKYLINE<br>BUSH, LINK     |
| <br><b>LHC0340</b><br>54570-50A10<br>SENTRA E16<br>SUSP. BUSH    | <br><b>LHC0344</b><br>54476-D0100<br>STANZA<br>SUSPENSION BUSH        | <br><b>LHC2016</b><br>54535-V1010<br>180B<br>SUSP. BUSH                  |
| <br><b>LHC3331</b><br>54570-50Y11<br>SENTRA '90<br>ARM BUSH      | <br><b>LHC0345</b><br>54535-D0101<br>STANZA<br>SUSPENSION BUSH       | <br><b>LHC2973</b><br>54535-V5000<br>Y30<br>SUSPENSION BUSH             |
| <br><b>LHC4345</b><br>54570-0M000<br>SENTRA B16<br>SUSP. BUSH  | <br><b>LHC3420</b><br>55045-D0101<br>BLUEBIRD<br>BUSH, LINK         | <br><b>LHC5422</b><br>54542-G5100<br>VAN '86<br>ARM BUSH, UPPER        |
| <br><b>LHC3434-11</b><br>54590-85E00<br>CEFIRO<br>ARM BUSH     | <br><b>LHC3987</b><br>55045-M7001<br>PULSAR 81-84<br>ARM BUSH, REAR | <br><b>LHC0513</b><br>54506-B9500<br>720<br>LINK BUSH, UP              |
| <br><b>LHC4486</b><br>54570-0E010<br>CEFIRO '96<br>SUSP. BUSH  | <br><b>LHC0462</b><br>54506-V0100<br>CEDRIC<br>SUSP. BUSH           | <br><b>LHC0514</b><br>54423-B9500<br>720<br>ARM BUSH, LOWER           |
| <br><b>LHC4461</b><br>54476-35F20<br>CEFIRO<br>CASTER BUSH     | <br><b>LHC3038</b><br>54505-V0102<br>CD430<br>ARM BUSH, LOWER       | <br><b>LHC4258</b><br>54560-01G00<br>D21 '93 E24, Z24<br>ARM BUSH     |

**TOYOTA** Replace parts

# SUSPENSION BUSH

|                                                                                    |                                                         |                                                                                     |                                                                           |                                                                                      |                                                               |
|------------------------------------------------------------------------------------|---------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------|
|    | LHC3602<br>48655-20030<br>COROLLA AE80<br>ARM BUSH      |    | LHC4512<br>18x54x60<br>48061-60010<br>ARM BUSH, LOWER                     |     | LHC4160<br>48854-22030<br>CRESSIDA RX100<br>ARM BUSH, LOWER   |
|    | LHC3673<br>48725-32080<br>AE80<br>ARM BUSH, LOWER       |    | 16x65x50<br>48702-60020<br>HJ75<br>LOWER ARM BUSH                         |     | LHC4483<br>48702-22370<br>CRESSIDA<br>LINK BUSH               |
|    | LHC2067<br>48654-12070<br>TOYOTA<br>SUSPENSION BUSH     |    | LHC4565<br>48702-60031<br>LAND C. 91-97<br>LINK BUSH, R                   |     | LHC4386<br>48702-22380<br>CRESSIDA RX100<br>BUSH              |
|    | LHC2066<br>48654-20050<br>TOYOTA<br>SUSPENSION BUSH     |    | 48702-60040<br>LANDCRUISER 91-97<br>LINK BUSH, R                          |     | LHC1567<br>48854-18041<br>TERCEL 84<br>ARM BUSH               |
|    | LHC4250<br>48655-12080<br>COROLLA '92<br>ARM BUSH       |    | LHC4511<br>16x60x50<br>48702-60050<br>HZJ80<br>LOWER ARM BUSH             |     | LHC4546<br>48654-16050<br>TERCEL 87-90<br>ARM BUSH, F         |
|    | LHC4251<br>48075-12031<br>COROLLA '94<br>ARM BUSH, ASSY |    | LHC4105<br>ORIGINAL QUALITY<br>48674-12090<br>CAMRY '88<br>STRUT ARM BUSH |     | LHC4463<br>48725-16150<br>TERCEL '95<br>MEMBER BUSH, R        |
|  | LHC4252<br>48076-12031<br>COROLLA '94<br>ARM BUSH ASSY  |  | LHC3603<br>48655-12010<br>CAMRY, COROLLA 88<br>ARM BUSH                   |  | LHC4537<br>48655-16050<br>TERCEL '95<br>ARM BUSH              |
|  | LHC3611<br>48655-20060-LH<br>CORONA<br>ARM BUSH         |  | LHC4509<br>48654-32040<br>CAMRY 88-91<br>ARM BUSH, F                      |  | LHC4189<br>48635-28010<br>KN20 84-93<br>ARM BUSH              |
|  | LHC3610<br>48655-20060-RH<br>CORONA<br>ARM BUSH         |  | LHC2974<br>48632-30070<br>CROWN<br>SUSP. BUSH                             |  | LHC4502<br>48061-27011<br>TOYOTA 5K'87<br>ARM BUSH, LOWER     |
|  | LHC4184<br>48655-20140<br>CORONA '92<br>ARM BUSH        |  | LHC2574<br>48654-35010<br>RN30<br>ARM BUSH                                |  | LHC4555<br>ORIGINAL QUALITY<br>48632-35050<br>ARM BUSH, UPPER |

# SUSPENSION BUSH

**MAZDA** Replace parts



LHC0144  
B210-34-470  
MAZDA 323'86  
SUSP. BUSH



LHC0147  
B092-34-460B  
323'86  
SUSPENSION BUSH



LHC3587  
B455-34-46XA  
MAZDA 323'90  
ARM BUSH, RH



LHC3588  
B455-34-46YA  
MAZDA 323'90  
ARM BUSH, LH



LHC2891  
B450-34-470  
MAZDA 323 '90  
SUSP. BUSH



LHC4563  
BC1F-34-46Y  
LIATA'95  
ARM BUSH, LH  
LHC4564



BC1F-34-46X  
LIATA'95  
ARM BUSH, RH



LHC4410  
BC1D-34-470  
LIATA'95  
ARM BUSH



LHC3214  
20x34x36  
B001-28-601FB  
323 80-86  
LINK BUSH  
LHC3213



B001-28-603FB  
323 80-86  
LINK BUSH



LHC0153  
G030-34-460C  
626 83-86  
ARM BUSH



LHC3210  
G030-34-470C  
MAZDA 626'83  
SUSPENSION BUSH



LHC2201  
GJ21-34-460B  
626'88  
SUSP. BUSH



LHC2202  
KA10-34-470A  
626'88  
SUSP. BUSH



LHC3556  
G211-34-460  
MX6 88-92  
ARM BUSH



LHC3732  
GA2A-34-46YA  
MAZDA 626'92  
SUSP. BUSH, LH



LHC3759  
GA2A-34-46XA  
MAZDA 626'92  
SUSPENSION BUSH, RH



LHC4022  
GA2B-34-470  
626'92  
SUSPENSION BUSH



LHC4413  
KY01-34-480  
FESTIVE 86-95  
ARM BUSH



LHC4423  
KD101-34-480  
FESTIVE 96  
ARM BUSH




LHC4228  
8173-34-480  
626 '80  
ARM BUSH



LHC4151  
H001-34-480  
929'82  
ARM BUSH



LHC4211  
H260-34-480  
929 88-91  
ARM BUSH



LHC4369  
929'92  
ARM BUSH  
LHC4368  
H380-34-460  
929'92  
ARM BUSH, F



LHC0907  
MAZDA B1800  
UPPER SHAFT BUSH



LHC2244  
0193-34-820  
B1600  
SUSP. BUSH



LHC3909  
UA01-34-820  
B2000  
SUSPENSION BUSH




LHC0185  
1391-34-820  
MAZDA E1800  
SUSP. BUSH



LHC3935  
UC86-34-460A  
B2200  
SUSPENSION BUSH

# SUSPENSION PARTS

**HONDA** Replace parts

|                                                                                                                                                                                                           |                                                                                                                                                          |                                                                                                                                                      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC0850</b><br>51396-059-000<br>CIVIC, ACCORD<br>SUSP. BUSH                                                        | <br><b>LHC4101</b><br>CIVIC '88<br>UPPER ARM BUSH                       | <br><b>LHC4774</b><br>51393-SV1-A01<br>ACCORD '95<br>ARM BUSH, F    |
| <br><b>LHC4253</b><br>51392-671-000<br>ACCORD '76-82<br>ARM BUSH                                                          | <br><b>LHC4221</b><br>HONDA '90<br>UPPER ARM BUSH                       | <br><b>LHC4556</b><br>51393-SM4-013<br>ACCORD '90-93<br>ARM BUSH    |
| <br><b>LHC0862</b><br>51392-SA5-000<br>CIVIC, ACCORD<br>SUSP. BUSH                                                        | <br><b>LHC4490</b><br>52622-SH3-004<br>CIVIC '88-99<br>REAR BUSH        | <br><b>LHC4220</b><br>51810-SM4-003<br>ACCORD '90<br>ARM BUSH       |
| <br><b>LHC1892</b><br>51396-SB2-003<br>HONDA '85<br>ARM BUSH                                                              | <br><b>LHC4439</b><br>52395-SH3-004<br>CIVIC '88-96<br>LINK BUSH        | <br><b>LHC4581</b><br>52384-SM4-000<br>ACCORD '90<br>REAR ARM BUSH |
| <br><b>LHC0946-AB</b><br>51455-SB0-B&S<br>ACCORD '86<br>ARM BUSH & SEAL                                                    | <br><b>LHC4441</b><br>52393-SR0-004<br>CIVIC '92-99<br>REAR BUSH        | <br><b>LHC4440</b><br>52365-SM4-004<br>ACCORD '90<br>BUSH REAR     |
| <br><b>LHC0946</b><br>51452-SB2-000-2<br>51455-SB0-003-2<br>51458-SB0-003-2<br>51453-SE0-000-1<br>ACCORD '86 ARM BUSH KIT | <br><b>LHC4492</b><br>52365-SH3-000<br>CIVIC '88-95<br>REAR ARM BUSH    | <br><b>LHC4491</b><br>52622-SM4-003<br>ACCORD '90<br>REAR BUSH      |
| <br><b>LHC4143</b><br>51810-SE0-003<br>ACCORD '86<br>ARM BUSH                                                           | <br><b>LHC4489</b><br>51392-SR3-004<br>CIVIC '92<br>LOWER ARM BUSH IN | <br><b>LHC4247</b><br>51395-SR3-N02<br>CIVIC '92<br>BUSH RH       |
| <br><b>LHC4460</b><br>52393-SE0-030<br>ACCORD '86-89<br>REAR BUSH                                                       | <br><b>LHC4152</b><br>51810-SH3-004<br>CIVIC '88-92-96<br>ARM BUSH    | <br><b>LHC4248</b><br>51396-SR3-N02<br>CIVIC '92<br>BUSH LH       |
| <br><b>LHC4501</b><br>52384-SE0-000<br>ACCORD '86<br>REAR ARM BUSH                                                      | <br><b>LHC4582</b><br>CIVIC '97<br>ARM BUSH                           | <br><b>LHC4600</b><br>51391-S04-005<br>CIVIC '97<br>ARM BUSH     |
| <br><b>LHC3726</b><br>52370-SH3-BUSH<br>CIVIC '96<br>BUSH, REAR ARM                                                     | <br><b>LHC4583</b><br>CIVIC '97<br>ARM BUSH                           | <br><b>LHC4484</b><br>10.5x34x48<br>CIVIC '96<br>ARM BUSH        |


# SUSPENSION PARTS

**mitsubishi** Replace parts

|                                                                                    |                                                       |                                                                                     |                                                                 |                                                                                      |                                                           |
|------------------------------------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------------------------------------------------|
|    | LH-2869<br>MB111040<br>GALANT<br>BUSH                 |    | LHC3562<br>16.2x38x42.5<br>MB303787<br>MIRAGE 84-87<br>ARM BUSH |     | LHC4146<br>MB518746<br>MITSUBISHI '86<br>ARM BUSH, LH     |
|    | LHC2890<br>MB110720<br>LANCER A171<br>ARM BUSH, LOWER |    | LHC3563<br>MB430385<br>MIRAGE 84-87<br>ARM BUSH                 |     | LHC4147<br>MB518747<br>MITSUBISHI '86<br>ARM BUSH, RH     |
|    | LHC4128<br>MB109786<br>LANCER 83-89<br>TRACK ARM BUSH |    | LHC4279<br>MB515143<br>MITSUBISHI<br>SUSPENSION BUSH, R         |     | LHC4067<br>MB808909<br>MIRAGE, LANCER '92<br>ARM BUSH, LH |
|    | LHC4091<br>MB002888<br>MITSUBISHI<br>BUSH             |    | LHC3841<br>MB573524<br>LANCER C62A<br>SUSPENSION BUSH           |     | LHC4068<br>MB808910<br>MIRAGE, LANCER '92<br>ARM BUSH, RH |
|    | LHC4081<br>MB110815<br>LANCER<br>TOP BUSH             |    | LHC4412<br>MB584084<br>LANCER '93 V62A<br>LINK BUSH             |    | LHC4397<br>MB809220<br>LANCER 93-95<br>LINK, REAR LH      |
|    | LHC4092<br>MB002979<br>MITSUBISHI<br>BUSH             |    | MB809231<br>LANCER '93<br>REAR ARM, RH                          |     | LHC4325<br>MR102013<br>LANCER '93<br>LINK BUSH            |
|  | LHC4185<br>MB003019<br>GALANT A161/3<br>ARM BUSH      |   | LHC4327<br>MB809239<br>LANCER '93<br>ARM BUSH, R                |  | LHC4398<br>MB809221<br>LANCER 93-95<br>LINK, REAR RH      |
|  | LHC0617<br>MB178020<br>VARICA CM66<br>SUSP. BUSH      |  | LHC4411<br>MR102063<br>LANCER '93<br>REAR ARM BUSH              |  | LHC4399<br>MB809222<br>LANCER 93-95<br>LINK, LH           |
|  | LHC4278<br>MB515500<br>MITSUBISHI<br>REAR BUSH        |  | LHC4245<br>MB109684<br>MONTERO, L200 84-95<br>ARM BUSH, UPPER   |  | LHC4400<br>MB809223<br>LANCER 93-95<br>LINK, RH           |
|  | LHC4407<br>MB518220<br>GALANT 89-93<br>ARM BUSH, F    |  | LHC4335<br>MB109682<br>L200 87-93<br>ARM BUSH, LOWER            |   | LHC4304<br>MB430145<br>DELICA L300 '88<br>ARM BUSH, LOWER |

# SUSPENSION PARTS

## DAIHATSU Replace parts

|                                                                                    |                                                          |
|------------------------------------------------------------------------------------|----------------------------------------------------------|
|    | LHC2334<br>45425-87501<br>S70, G11<br>IDLE BUSH          |
|    | LHC2439<br>48674-87703<br>G11<br>ARM BUSH                |
|    | LHC4025<br>48674-87704<br>CHARADE G100<br>ARM BUSH FRONT |
|    | LHC4191<br>48654-87703<br>G100<br>ARM BUSH               |
|    | LHC4594<br>48729-87706<br>CHARADE 83-95<br>BUSH OF LINK  |
|   | 48730-87101<br>CHARADE 90-93<br>LINK, R REAR             |
|  | 48710-87705<br>CHARADE 90-93<br>LINK, R FRONT            |
|  | 48730-87708<br>G130<br>LINK                              |
|  | 48780-87706<br>G130<br>LINK                              |
|  | 48710-87706<br>G130<br>LINK                              |







## SUZUKI Replace parts

|                                                                                     |                                                          |
|-------------------------------------------------------------------------------------|----------------------------------------------------------|
|    | LHC0700<br>48750-79030<br>SUZUKI<br>IDLE BUSH            |
|    | LHC4389<br>48750-85000<br>SUZUKI<br>IDLE ARM BUSH        |
|    | LHC4339<br>09319-14007<br>VATARA 89-96<br>FRONT ARM BUSH |
|    | LHC4431<br>09319-12044<br>SJ413 89-96<br>FRONT ARM BUSH  |
|    | LHC4340<br>09319-12045<br>SJ413 89-96<br>REAR ARM BUSH   |
|    | LHC4341<br>09319-12043<br>SJ413 89-96<br>REAR LINK BUSH  |
|  | LHC4217<br>45530-60B00<br>SWIFT<br>ARM BUSH, F           |
|  | LHC4349<br>45540-60B02<br>SWIFT 1.3<br>ARM BUSH          |
|  | LHC4280<br>46420-60E00<br>SWIFT<br>ARM BUSH, REAR        |
|  | LHC4281<br>46430-60B00<br>SWIFT 1.3<br>REAR ARM BUSH     |

## ISUZU Replace parts

|                                                                                      |                                                            |
|--------------------------------------------------------------------------------------|------------------------------------------------------------|
|     | 8-94214-170<br>KB20<br>ARM BUSH                            |
|     | LHC0896<br>8-08952-179<br>PF60<br>ARM BUSH, REAR           |
|    | LHC0978<br>8-94213-295<br>ISUZU KB26<br>ARM BUSH, LOWER    |
|     | LHC2361<br>8-94226-557<br>ISUZU KB26<br>ARM BUSH, UPPER    |
|     | LHC2362<br>8-94223-386<br>ISUZU KB26<br>ARM BUSH, LOWER    |
|     | LHC4102<br>8-94408-840<br>TROOPER 89-93<br>ARM BUSH, UPPER |
|   | LHC4373<br>8-94408-841<br>TROOPER 84-91<br>ARM BUSH        |
|  | LHC1575<br>94408842<br>TROOPER 84-91<br>ARM BUSH LOWER, R  |
|   | LHC4084<br>5-51225-002<br>MONTERO<br>ARM BUSH, LOWER       |
|   | LHC4402<br>8-94106-435<br>I-MARK 85-89<br>ARM BUSH LOWER   |

# SUSPENSION PARTS


|                                                                                                                                                                              |                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC0119<br/>B001-28-500/600<br/>MAZDA 323 80-85<br/>LINK, ASSY RH/LH</p>                 |  <p>LHC4314<br/>48730-12010<br/>COROLLA 88-91<br/>LINK<br/>BUSH<br/>48725-12110</p>                                           | <p><b>ACCORD 1998<br/>REAR LINK</b></p>  <p>FRONT</p> <p>TRAILING ARM<br/>RH: LHC9079<br/>LH: LHC9080</p> <p>LOWER ARM<br/>LHC9076</p> <p>UPPER ARM<br/>LHC9075</p> <p>CONTROL ARM<br/>LHC9078</p> <p>LEADING ARM<br/>LHC9077</p> <p>TOP VIEW</p> |
|  <p>LHC0120<br/>B001-28-300A<br/>MAZDA 323 80-85<br/>LINK, ASSY</p>                          |  <p>LHC4313<br/>48710-12040<br/>COROLLA 88-91<br/>LINK, ASSY<br/>BUSH<br/>48725-12290</p>                                     |                                                                                                                                                                                                                                                                                                                                     |
|  <p>LHC2884<br/>B092-28-500B(RH)<br/>B092-28-550B(LH)<br/>323 86<br/>SUSP. ASSY, R RH/LH</p> |  <p>LHC4312<br/>48780-12010<br/>COROLLA 88-91<br/>LINK, ASSY<br/>BUSH<br/>LHC4315</p>                                         |                                                                                                                                                                                                                                                                                                                                     |
|  <p>LHC2885<br/>B092-28-600<br/>323 86-88<br/>LINK ASSY</p>                                  |  <p>48710-12200<br/>COROLLA 1993<br/>LINK<br/>48730-12110<br/>COROLLA 1993<br/>LINK<br/>LHC4312<br/>COROLLA 1993<br/>LINK</p> | <p>LHC7238<br/>GALANT '94<br/>BUSH OF REAR LINK<br/>MB864731 REAR LINK</p>                                                                                                                                                                                                                                                          |
|  <p>LHC2886<br/>B099-28-200<br/>323 86-88<br/>LINK ASSY</p>                                  |  <p>LHC4674<br/>48740-33010<br/>CAMRY '92<br/>LINK, LH</p>                                                                    | <p>ISUZU<br/>RODEO, AMIGO 1998</p> <p>8-97134-706<br/>8-97147-547<br/>8-97124-898<br/>LATERAL LINK<br/>8-97124-881<br/>LINK LOWER<br/>8-97125-086<br/>8-97134-705</p>                                                                                                                                                               |
|  <p>B455-28-620 RH<br/>B455-28-630 LH<br/>MAZDA 323 '90<br/>LINK</p>                        |  <p>LHC4674<br/>48740-33010<br/>CAMRY '92<br/>LINK, LH</p>                                                                   | <p>CHEVROLET TRACKER 89-01<br/>FRONT ARM<br/>96057767<br/>96057765</p>                                                                                                                                                                                                                                                              |
|  <p>LHC7010<br/>B455-28-600<br/>MAZDA 323 '90<br/>LINK, REAR</p>                           |  <p>LHC4558<br/>48725-12200<br/>CAMRY '92<br/>LINK BUSH</p>                                                                 | <p>CHEVROLET TRACKER 89-01<br/>REAR ARM<br/>96057766</p>                                                                                                                                                                                                                                                                            |
|  <p>LHC7011<br/>B455-28-200A<br/>MAZDA 323 '90<br/>LINK, TRAILING</p>                      |  <p>LHC4676<br/>48710-33020<br/>CAMRY '92-93<br/>LINK</p>                                                                   |  <p>LHC7019<br/>GA2A-28-500<br/>626 '93<br/>LINK, REAR</p>                                                                                                                                                                                        |
|  <p>LHC7019<br/>GA2A-28-500<br/>626 '93<br/>LINK, REAR</p>                                 |  <p>LHC4672<br/>48730-33010<br/>CAMRY '92-96<br/>LINK</p>                                                                   |  <p>LHC7032<br/>1329655<br/>VOLVO 740, 760<br/>LINK BUSH</p>                                                                                                                                                                                      |
|  <p>LHC7020<br/>G516-28-200<br/>626 '93<br/>LINK, REAR</p>                                 |  <p>48706-10020<br/>TERCEL 91-94 EP81<br/>LINK BUSH<br/>48740-10020<br/>TERCEL 91-94<br/>LINK</p>                           |  <p>LHC7032<br/>1329655<br/>VOLVO 740, 760<br/>LINK BUSH</p>                                                                                                                                                                                      |

# SUSPENSION PARTS

## RENAULT Replace parts

## PEUGEOT Replace parts








## FORD Replace parts

|                                                                                    |                                                             |
|------------------------------------------------------------------------------------|-------------------------------------------------------------|
|    | LHC0834<br>7704000681<br>R9, R11<br>SUSPENSION BUSH         |
|    | LHC3743<br>R19<br>SUSPENSION BUSH                           |
|    | LHC3258<br>14x27x51<br>7701348038<br>R12<br>ARM BUSH, UPPER |
|    | LHC3259<br>14x32x46<br>7700514109<br>R12<br>ARM BUSH, LOWER |
|    | LHC3261<br>7700547187<br>R12<br>SUSPENSION BUSH             |
|    | 7700626057<br>R4, R5, R6<br>BUSH                            |
|  | 7700542611<br>R5<br>BUSH                                    |
|  | 7700518856<br>R4, R5<br>ARM BUSH UPPER                      |
|  | LHC4784<br>7700819929A<br>RENAULT TWINGO<br>ARM BUSH        |
|  | LHC4785<br>7700831364<br>RENAULT TWINGO<br>ARM BUSH         |

|                                                                                     |                                                                          |
|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------|
|    | LHC1609<br>3561.04<br>PEUGEOT<br>BUSH                                    |
|    | LHC1913<br>ORIGINAL QUALITY<br>3523.23<br>PEUGEOT 305<br>SUSP. BUSH      |
|    | LHC2533<br>ORIGINAL QUALITY<br>3523.24<br>PEUGEOT 305<br>SUSP. BUSH      |
|    | LHC3490<br>ORIGINAL QUALITY<br>3523.40<br>PEUGEOT 405<br>SUSPENSION BUSH |
|    | LHC1603<br>3523.12<br>PEUGEOT<br>BUSH                                    |
|    | LHC1604<br>5171.04<br>PEUGEOT<br>BUSH                                    |
|  | LHC1605<br>5131.04<br>PEUGEOT 404<br>BUSH                                |
|  | LHC3265<br>3523.09<br>PEUGEOT<br>BUSH                                    |
|  | LHC1607<br>3523.10<br>PEUGEOT<br>BUSH                                    |
|  | LHC1608<br>3561.06<br>PEUGEOT<br>BUSH                                    |

|                                                                                      |                                                             |
|--------------------------------------------------------------------------------------|-------------------------------------------------------------|
|     | LHC0033<br>74BB-3068-AA<br>CORTINA<br>SUSP. BUSH, UPR       |
|     | LHC0034<br>74BB-3060-AB<br>CORTINA<br>SUSP. BUSH, LOR       |
|     | LHC0029<br>71BB-5K790-BB<br>CORTINA<br>SUSP. BUSH, R        |
|     | LHC0073<br>72GB-3068-AC<br>GRANADA GL<br>ARM BUSH, UPPER    |
|     | LHC4422<br>I.D. 12mm<br>74BC-5A103-AA<br>FORD<br>FRAME BUSH |
|    | LHC4421<br>77BC-5L021-AA<br>FORD MK5<br>FRAME BUSH          |
|   | LHC4194<br>81AB-3063-AA<br>FORD<br>ARM BUSH                 |
|   | LHC2437<br>85GB-5493-AB<br>SIERRA<br>SUSP. BUSH             |
|   | LHC4087<br>93BB-3063-AA<br>MONDEO<br>ARM BUSH FRONT         |
|  | LHC4488<br>MONDEO '94<br>ARM BUSH                           |

# STEERING RACK BOOT

|                                                                                                                                                               |                                                                                                                                                       |                                                                                                                                                              |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC3031<br/>48571-82000<br/>CULTUS<br/>STEERING BOOT, RH</p>              |  <p>LHC1675<br/>271544<br/>VOLVO<br/>STEERING BOOT</p>               |  <p>LHC1631<br/>4066.15/20<br/>PEUGEOT 205, 305, 504<br/>STEERING BOOT</p> |
|  <p>LHC3057<br/>48571-85001<br/>FORSA<br/>STEERING BOOT, LH</p>               |  <p>LHC1676<br/>271542<br/>VOLVO<br/>STEERING BOOT</p>               |  <p>LHC1632<br/>4066.17<br/>PEUGEOT<br/>STEERING BOOT</p>                  |
|  <p>LHC3032<br/>48572-82000<br/>CULTUS<br/>STEERING BOOT, LH</p>              |  <p>LHC3345<br/>1273412<br/>VOLVO 760<br/>STEERING BOOT, LH</p>      |  <p>LHC3709<br/>9x43x200<br/>USA CAR<br/>STEERING BOOT</p>                 |
|  <p>LHC0881<br/>9x44x190<br/>31232-GA082<br/>SUBARU<br/>STEERING BOOT</p>     |  <p>LHC3596<br/>1273413<br/>VOLVO 760<br/>STEERING BOOT, RH</p>      |  <p>LHC3421<br/>11X32X165<br/>FORD<br/>STEERING BOOT</p>                   |
|  <p>LHC3029<br/>18x29x90<br/>7312-32060<br/>SUBARU<br/>STEERING BOOT</p>      |  <p>LHC3708<br/>1228425<br/>VOLVO 240<br/>STEERING BOOT</p>          |  <p>LHC3913<br/>47.5x55x128<br/>GM CAMIRA<br/>STEERING BOOT</p>            |
|  <p>LHC3030<br/>13x29x93<br/>7312-32030<br/>SUBARU<br/>STEERING BOOT</p>     |  <p>LHC3912<br/>SAAB 9000<br/>STEERING BOOT</p>                     |  <p>LHC3914<br/>35.7x55x128<br/>GM CAMIRA<br/>STEERING BOOT</p>           |
|  <p>LHC2965<br/>MB122138<br/>MIRAGE 78-83<br/>STEERING BOOT</p>             |  <p>LHC2866<br/>321111117426<br/>BMW320<br/>STEERING BOOT</p>      |  <p>LHC0054<br/>71BB-3K661-BA<br/>CORTINA<br/>STEERING BOOT</p>          |
|  <p>LHC3043<br/>11x46x185<br/>MB501711<br/>MITSUBISHI<br/>STEERING BOOT</p> |  <p>LHC2128<br/>321111118104<br/>BMW320<br/>STEERING BOOT</p>      |  <p>LHC0055<br/>71BB-3K668-BA<br/>CORTINA<br/>STEERING BOOT</p>          |
|  <p>LHC3047<br/>11x45x162<br/>MB243386<br/>MITSUBISHI<br/>STEERING BOOT</p> |  <p>LHC0830<br/>7700678649<br/>R9<br/>STEERING BOOT</p>            |  <p>LHC1751<br/>11x58x190x15<br/>HOLDEN<br/>STEERING BOOT</p>            |
|  <p>LHC2858<br/>UNIVERSAL<br/>STEERING BOOT</p>                             |  <p>LHC3045<br/>7700653459<br/>R18, R21, R25<br/>STEERING BOOT</p> |  <p>LHC1752<br/>11x55x180x11<br/>HOLDEN<br/>P/STEERING BOOT</p>          |



# SUSPENSION PARTS

V.W., AUDI, OPEL, BMW, FIAT, BENZ, GM Replace parts




|                                                                                                                                                                    |                                                                                                                                                                                |                                                                                                                                                        |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC1781<br/>113-411-315<br/>VW<br/>SUSPENSION BUSH</p>                         |  <p>LHC3337<br/>90235040<br/>OPEL KADETT<br/>SUSP. BUSH</p>                                   |  <p>LHC2680<br/>7556563<br/>FIAT 85S<br/>SUSP. BUSH</p>               |
|  <p>LHC1746<br/>411-417-325<br/>V.V<br/>SUSP. BUSH</p>                             |  <p>LHC3336<br/>90235043-1<br/>ASTRA, KADETT<br/>SUSP. BUSH LOWER</p>                         |  <p>LHC3520<br/>5927292<br/>UNO<br/>ARM BUSH</p>                      |
|  <p>LHC1745<br/>113-415-441<br/>V.V. BEETLE<br/>SUSPENSION BUSH</p>                |  <p>LHC3755<br/>90-279-437<br/>OPEL 2.0<br/>SUSPENSION BUSH</p>                               |  <p>LHC3521<br/>5927293<br/>UNO<br/>ARM BUSH</p>                     |
|  <p>LHC3839<br/>17x60x41<br/>191-407-181<br/>JETTA, GOLF, MODERNO<br/>ARM BUSH</p> |  <p>LHC3756<br/>90-279-193<br/>OPEL 2.0<br/>SUSPENSION BUSH</p>                               |  <p>LHC4139<br/>19x65x160<br/>TIMAR<br/>ARM BUSH</p>                 |
|  <p>LHC4182<br/>357-407-181<br/>PASSAT<br/>ARM BUSH</p>                            |  <p>LHC3755-58<br/>352348<br/>VECTRA '94<br/>ARM BUSH</p>                                     |  <p>LHC1944<br/>12.5x24x23<br/>80621<br/>ROVER<br/>LINK BUSH, IPR</p> |
|  <p>LHC4181<br/>357-407-182<br/>PASSAT<br/>ARM BUSH</p>                            |  <p>LHC3339-11<br/>352346<br/>ASTRA '94<br/>ARM BUSH LOWER</p>                                |  <p>LHC2036<br/>ACB9274<br/>ROVER<br/>LINK BUSH, LOWER</p>            |
|  <p>LHC4559<br/>191-407-181E<br/>POLO<br/>ARM BUSH</p>                           |  <p>LHC4786<br/>90445571<br/>OMEGA 2.5<br/>ARM BUSH</p>                                     |  <p>LHC4086<br/>126-352-0165<br/>BENZ 123<br/>AXLE BUSH</p>         |
|  <p>LHC4557<br/>POLO<br/>ARM BUSH</p>                                            |  <p>LHC4518<br/>31121124622<br/>BMW 520 88-95<br/>ARM BUSH</p>                              |  <p>LHC4086<br/>2805510<br/>CHEV<br/>ARM BUSH, UPPER</p>            |
|  <p>LHC4255<br/>2-22-000238-01<br/>AUDI 80<br/>ARM BUSH</p>                      |  <p>LHC4519<br/>ORIGINAL QUALITY<br/>31121136605<br/>BMW 88-95<br/>ARM BUSH -OIL INSIDE</p> |  <p>LHC4085<br/>2807244<br/>CHEV<br/>ARM BUSH, LOWER</p>            |
|  <p>LHC4525<br/>481-407-188<br/>AUDI 100 91-92<br/>ARM BUSH</p>                  |  <p>LHC4526<br/>440-407-183<br/>AUDI 100 '93<br/>ARM BUSH</p>                               |  <p>LHC4524<br/>4626446<br/>CHRYSLER NEON '95<br/>ARM BUSH, F</p>   |

# CV JOINT BOOT

OVER 100 DIFFERENT SIZE

|                                                                                    |                                                                                 |                                                                                     |                                                                                  |                                                                                     |                                                                                  |
|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|
|    | 39241-50A25/7<br>39241-03A25<br>NISSAN 1.3-1.7<br>SUNNY, PULSAR<br>BLUEBIRD U12 |    | LHCV2043<br>43447-32010<br>43447-32021<br>43447-17040<br>TOYOTA 1.8/2.0          |    | LHC0141<br><br>F006-22-530<br>MAZDA 323'86<br>OUTER                              |
|    | LHCV2058<br>39741-02A26/8<br>NISSAN 1.3-1.7<br>SUNNY, PULSAR<br>BLUEBIRD U12    |    | LHCV2044<br>43448-32010/20<br>TOYOTA 1.8/2.0<br>CAMRY, COROLLA<br>CARINA, CORONA |    | LHC0142<br><br>F006-22-540<br>MAZDA 323'86<br>INNER                              |
|    | LHC0315<br><br>39241-01A01<br>NISSAN 82-85<br>B11, E13, E15                     |    | LHCV2049<br>43447-12020<br>43447-17020<br>TOYOTA 1.5/1.6<br>CORONA, COROLLA      |    | 44333-SB2-981<br>HONDA 1.6-2.0<br>ACCORD, PRELUDE<br>VIGOR, BALLADE<br>CIVIC '85 |
|    | LHC3424<br>39241-16R00<br>MB297370<br>8-94258-285<br>G001-22-530                |    | LHCV2050<br>43448-12020<br>TOYOTA 1.5/1.6<br>CORONA, COROLLA<br>CARINA, CELICA   |    | LHCV2011<br>44333-SA2-310<br>44325-SB0-300<br>7232-22011                         |
|    | LHCV2061<br>39241-01E00/25<br>NISSAN 1.6-2.0<br>AUSTER, BLUEBIRD<br>STANZA '85  |    | LHCV2042<br>04438-20010<br>04438-32050<br>G002-22-540<br>MB160658                |    | LHCV2032<br><br>44333-SA5-003/4<br>HONDA '85<br>OUTER                            |
|   | LHCV2062<br>39741-01E00/25<br>NISSAN 1.6-2.0<br>AUSTER, BLUEBIRD<br>STANA '85   |   | 44119-78010<br>7232-22250<br>04438-87705<br>04438-87204<br>42324-679-023         |   | LHCV2003<br>44333-634-013<br>40088-M0820<br>6232-07183/4                         |
|  | LHCV2021<br><br>39241-D0101<br>NISSAN 81-85<br>STANZA, AUSTER                   |  | LHCV2048<br>MB176861<br>MB297339<br>MB393130<br>MB297454                         |  | LHCV2017<br>44118-82610<br>44118-82350<br>44118-78022<br>SUZUKI                  |
|  | LHCV2022<br><br>39741-D0101<br>NISSAN 81-85<br>STANZA, AUSTER                   |  | LHCV2080<br><br>MB297337<br>MIRAGE<br>OUTER                                      |  | LHCV2029<br><br>7232-22043<br>SUBARU 4WD<br>INNER                                |
|  | LHC3427<br>39241-10E26<br>NISSAN<br>BLUEBIRD ATM<br>OUTER                       |  | 8-94153-133<br>F001-22-530<br>39241-11M00<br>23222-GA140<br>MB297351             |  | LHC1777<br><br>171-407-283<br>GOLF, AUDI<br>CV JOINT BOOT                        |
|  | LHC0166<br><br>5-43319-019<br>G001-22-540<br>39741-16R00                        |  | 8-94124-210<br>04438-20010<br>04438-32050<br>G002-22-530<br>23222-GA111          |  | LHC3411<br><br>321-407-285<br>JETTA, GOLF<br>CV JOINT BOOT                       |

# RADIATOR HOSE, BYPASS & HEATER HOSE JAPANESE CAR

|                                                                                                                                                                  |                                                                                                                                                            |                                                                                                                                                             |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC2605<br/>E5D3-15-186A<br/>CE503-15-186<br/>323'86-'88<br/>HOSE, UPPER</p> |  <p>LHC2219<br/>33x590<br/>21501-54A10<br/>CD17<br/>RADI. HOSE, UPPER</p> |  <p>LHC3006<br/>19501-PM3-000<br/>ACCORD<br/>RADI. HOSE, UPPER</p>         |
|  <p>LHC0095<br/>B308-15-185<br/>323'88<br/>RADI. HOSE, LOWER</p>                 |  <p>LHC2218<br/>21504-54A00<br/>NISSAN CD17<br/>RADI. HOSE, LOWER</p>     |  <p>LHC3440<br/>19502-PM3-000<br/>ACCORD 16V<br/>HOSE, LOWER</p>           |
|  <p>LHC2675<br/>29X550<br/>B366-15-186A<br/>323'90<br/>HOSE, UPPER</p>           |  <p>LHC3365<br/>21501-53Y00<br/>SENTRA '90<br/>HOSE, UPPER</p>            |  <p>LHC3075<br/>16571-72020<br/>HIACE 3Y, 4Y '82<br/>RADI. HOSE, UPPER</p> |
|  <p>LHC2676<br/>29X330<br/>B366-15-185A<br/>323'90<br/>HOSE, LOWER</p>           |  <p>LHC3361<br/>21503-53Y00<br/>SENTRA '90<br/>HOSE, LOWER</p>            |  <p>LHC3076<br/>16572-72020<br/>HIACE 3Y, 4Y '82<br/>RADI. HOSE, LOWER</p> |
|  <p>LHC2181<br/>F8C1-15-186<br/>626'88<br/>RADI. HOSE, UPR</p>                   |  <p>LHC3073<br/>21501-01B60<br/>MARCH '82<br/>RADI. HOSE, UPPER</p>       |  <p>LHC3384<br/>16571-54120<br/>TOYOTA L<br/>HOSE, UPPER</p>               |
|  <p>LHC0065<br/>F201-15-185<br/>626'88<br/>RADI. HOSE, LOR</p>                   |  <p>LHC3074<br/>21503-01B60<br/>MARCH '82-'84<br/>RADI. HOSE, LOWER</p>   |  <p>LHC3385<br/>16572-54090<br/>TOYOTA L<br/>HOSE, LOWER</p>               |
|  <p>LHC3350<br/>RF01-15-186A<br/>B2200<br/>RADI. HOSE, UPPER</p>                |  <p>LHC0521<br/>21501-02W00<br/>720<br/>RADI. HOSE, UPR</p>              |  <p>LHC3386<br/>16571-37040<br/>CRESSIDA ERX60<br/>HOSE, UPPER</p>        |
|  <p>LHC3351<br/>R201-15-185B<br/>B2200<br/>RADI. HOSE, LOWER</p>               |  <p>LHC0522<br/>21503-02W00<br/>720<br/>RADI. HOSE, LOR</p>             |  <p>LHC3387<br/>16572-37030<br/>CRESSIDA ERX60<br/>RADI. HOSE, LOWER</p> |
|  <p>LHC3098<br/>92413-01A10<br/>NISSAN<br/>HEATER HOSE</p>                     |  <p>LHC3077<br/>21501-02N00<br/>NISSAN TD23<br/>RADI. HOSE, UPPER</p>   |  <p>LHC0756<br/>16571-56020<br/>V22<br/>RADI. HOSE, UPR</p>              |
|  <p>LHC3368<br/>92400-01A01<br/>NISSAN<br/>HEATER HOSE</p>                     |  <p>LHC3078<br/>21503-02N00<br/>NISSAN TD23<br/>RADI. HOSE, LOWER</p>   |  <p>LHC0757<br/>16572-56030<br/>V22<br/>RADI. HOSE, LOR</p>              |

# RADIATOR HOSE, BYPASS & HEATER HOSE

|                                                                                    |                                                        |                                                                                     |                                                          |                                                                                      |                                                             |
|------------------------------------------------------------------------------------|--------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------|
|    | LHC2534<br>7700757553<br>R11<br>RADI. HOSE, UPPER      |    | LHC3048<br>VOLVO 760<br>HOSE, UPPER                      |    | LHC2198<br>811-819-371B<br>VW AUDI '80<br>WATER HOSE        |
|    | LHC2535<br>7700759170<br>R11<br>RADI. HOSE, LOR        |    | LHC3049<br>VOLVO 760<br>HOSE, LOWER                      |     | LHC2196<br>059-121-057E<br>VW AUDI '80<br>WATER HOSE        |
|    | LHC1621<br>1343.25<br>PEUGEOT 504<br>RADI. HOSE, UPR   |    | LHC3173<br>24X260<br>056-121-053B<br>GOLF<br>HOSE        |    | LHC1772<br>049-121-123A<br>AUDI<br>WATER HOSE               |
|    | LHC1624<br>1350.32<br>PEUGEOT 504<br>RADI. HOSE, LOR   |    | LHC3174<br>10X16X340<br>026-121-058C<br>GOLF<br>HOSE     |    | LHC1180<br>MC426126<br>FK, FM<br>RADI. HOSE, UPR            |
|    | LHC1897<br>1343.65<br>PEUGEOT 305<br>RADI. HOSE, UPPER |    | LHC1771<br>055-121-063A<br>GOLF<br>WATER HOSE            |    | LHC1161<br>MC426143<br>FK, FM<br>RADI. HOSE, LOR            |
|    | LHC1898<br>1350.56<br>PEUGEOT 305<br>RADI. HOSE, LOWER |    | LHC1773<br>171-121-611E<br>GOLF 1.5<br>WATER HOSE        |    | LHC1162<br>MC426147<br>FK, FM<br>RADI. HOSE, LOR            |
|  | LHC3050<br>BMW520i<br>HOSE, UPPER                      |  | LHC1769<br>035-121-057F<br>VW PASSAT<br>WATER HOSE       |  | LHC3397<br>1-21437-274<br>FTR<br>HOSE, UPPER                |
|  | LHC3051<br>BMW520i<br>HOSE, LOWER                      |  | LHC1770<br>049-121-123<br>VW PASSAT<br>WATER HOSE        |   | LHC3398<br>1-09360-740<br>FTR<br>HOSE, LOWER                |
|  | LHC3052<br>BMW520i<br>HOSE, LOWER                      |  | LHC1774<br>056-121-063A<br>VW PASSAT<br>WATER HOSE       |  | LHC3079<br>52X49X500<br>9001-44654B<br>EK100<br>HOSE, UPPER |
|  | LHC3340<br>31x41x570<br>VOLVO 340<br>RADI. HOSE, LOWER |  | LHC1775<br>049-121-058F<br>VW GOLF 1.5/1.6<br>WATER HOSE |  | LHC3080<br>49X500<br>9001-44694<br>EK100<br>HOSE, LOWER     |



LHC0118  
8118-40-061  
MAZDA 323  
MUFFLER HANG



LHC0182  
3874-40-060  
MAZDA 929  
MUFFLER HANG



LHC0298  
20640-01A01  
B11  
MUFFLER SUPPORT



LHC0222  
40x66  
UNIVERSAL  
MUFFLER RING



LHC2679  
20630-H5000  
SUNNY  
MUFFLER SUPPORT



LHC0268  
20630-G1001  
PICKUP  
MUFFLER SUPPORT



LHC0349  
20650-D0100  
STANZA  
MUFFLER SUPPORT



LHC2986  
20650-01B01  
NISSAN  
MUFFLER SUPPORT



LHC2900  
20636-N4600  
E23, Z20  
MUFFLER SUPPORT



LHC0887  
17567-87704  
CHARADE  
MUFFLER SUPPORT



LHC0866  
18215-671-000  
CIVIC  
MUFFLER SUPPORT



LHC0877  
18215-SA0-960  
BALLADE  
MUFFLER HANG



LHC3058  
17565-13030  
TOYOTA KM20  
MUFFLER SUPPORT



LHC3015  
17567-58010  
BU85  
MUFFLER HANGER



LHC3014  
17563-58010  
BU85  
MUFFLER HANGER



LHC3016  
17567-61030  
BU85, FJ60  
MUFFLER HANGER



LHC3021  
17565-71050  
HIACE  
MUFFLER SUPPORT



LHC3022  
17566-71041  
HIACE  
MUFFLER SUPPORT



LHC3013  
8-94156-256  
NPR  
MUFFLER SUPPORT



LHC1782  
211-251-245  
VW  
MUFFLER SUPPORT



LHC1917  
77FB-5A262CA  
SIERRA  
MUFFLER SUPPORT



LHC0058  
72GB-5281-AA  
CORTINA  
MUFFLER SUPPORT



LHC0828  
7700686449  
R9  
MUFFLER SUPPORT



LHC0829  
7700677733L  
R9  
MUFFLER SUPPORT



LHC1669  
7700558542  
R5  
MUFFLER SUPPORT



LHC1616  
3304.60  
PEUGEOT  
MUFFLER SUPPORT



LHC2129  
49\*85\*19  
BMW  
MUFFLER SUPPORT



LHC1667  
116 492  
BENZ  
MUFFLER SUPPORT



LHC1677  
1206468  
VOLVO  
MUFFLER SUPPORT



LHC2667  
21B144  
ROVER  
MUFFLER SUPPORT



LHC0263

UNIVERSAL  
GEAR SHIFT BOOT



LHC0322

74960-01A00  
UNIVERSAL, B11  
GEAR LEVER BOOT



LHC2193

96935-50A00  
SENTRA B12  
GEAR SHIFT BOOT



LHC0561

75950-T7800  
SD22  
GEAR SHAFT BOOT



LHC2291

58280-30030  
LANDCRUISER  
GEAR SHAFT BOOT



LHC0752

33555-87702  
V22  
GEAR SHIFT BOOT



LHC1684

123 267 0097  
BENZ  
GEAR SHAFT BOOT



LHC3057

1-79997-144  
V10  
CHANGE LEVER BOOT



LHC0535

34115-P0101  
HOMER  
GEAR INSULATOR



LHC2983

34115-R8000  
NISSAN  
GEAR INSULATOR



LHC3438

0604-46-684  
B1800  
GEAR SHIFT BUSH



LHC2953

32825-H1010  
SUNNY  
GEAR SHIFT BUSH



LHC2954

32861-N4200  
SUNNY  
GEAR SHIFT BUSH



LHC3374

34139-01A00  
B11  
GEAR BUSH



LHC0324

34138-W7060  
SENTRA B11  
GEAR SHIFT BUSH



LHC3422

34139-01E10  
BLUEBIRD  
GEAR SHIFT BUSH



LHC2055

34552-89900  
NISSAN  
GEAR SHIFT BUSH



LHC1943

FAM2406  
ROVER  
GEAR SHIFT BUSH



LHC2933

MALAGA  
GEAR SHIFT BUSH



LHC1330

2-851-5109-00  
HINO KB, NE  
GEAR BUSH



LHC0305

SENTRA B11  
GEAR SHIFT KIT



LHC2213

B001-46-041  
B001-46-062, 090  
MAZDA 323'86  
GEAR SHIFT KIT



LHC0735

MAZDA E3000  
GEAR SHAFT KIT



LHC2934

PEUGEOT 305  
GEAR SHIFT KIT



LHC2865

R9  
GEAR SHIFT KIT



LHC0612

L300  
GEAR SHAFT KIT



LHC0295

34560-01A00  
B11  
HAND GEAR HOLDER




LHC0346

34561-D0100  
34562-D0100  
STANZA  
GEAR LEVER MOUNT



LHC2935

B12  
GEAR SHIFT KIT



LHC4495

06542-SH3-010  
CIVIC 85-95  
GEAR SHAFT KIT

# IDLE ARM BUSH



LHC0180  
UA01-32-329  
MAZDA E1600  
IDLE BUSH



LHC2255  
0208-32-326  
MAZDA B1600  
IDLE BUSH



LHC0700  
48750-79030  
SUZUKI  
IDLE BUSH



LHC0247  
48544-H1000  
SUNNY  
IDLE BUSH



LHC0487  
48544-01L00  
NISSAN SKYLINE  
IDLE BUSH



LHC4060  
48544-G3700  
NISSAN VANETTE  
ARM BUSH



LHC0566  
31257-6402P  
SD22  
IDLE BUSH



LHC2334  
45425-87501  
S70, G11  
IDLE BUSH



LHC3027  
90385-18068  
3Y  
IDLER ARM BUSH



LHC3100  
90386-25075  
HIACE  
CENTER ARM BUSH

# FRAME BUSH



LHC0027  
748B-5L021-AA  
CORTINA  
FRAME BUSH



LHC0028  
748B-5A103-AA  
CORTINA  
FRAME BUSH



LHC0081  
72GB-5A103-BB  
GRANADA GL  
FRAME BUSH



LHC2864  
54466-V5003  
Y30  
BUSH



LHC2863  
54467-V5001  
Y30  
INSULATOR



LHC3101  
54460-V5000  
NISSAN  
INSULATOR



LHC3102  
54462-V5000  
NISSAN  
INSULATOR



LHC3482  
55466-W1200  
NISSAN  
BUSH



LHC3503  
B092-39-811  
MAZDA 323'86  
INSULATOR



LHC3504  
B092-36-811  
MAZDA 323'86  
INSULATOR

# SUSPENSION BUMPER



LHC0296  
55240-01A00  
SUNNY 83-90  
SUSPENSION BUMPER



LHC0518  
55240-01W00  
PICKUP 720 81-90  
SPRING BUMPER



LHC4602  
54050-01G00  
D21'93  
ARM BUMPER



LHC4234  
55240-R8201  
Z20, E23  
SPRING BUMPER



LHC3444  
48435-36050  
DYNA B085 85-94  
HELPER, SPRING



LHC0761  
48435-87303  
DELTA V22  
BUMPER, HELPER



LHC0760  
48331-87304  
V22  
SPRING BUMPER



LHC0745  
T4100  
SPRING BUMPER, F




LHC0746  
W025-28-330  
T4100  
SPRING BUMPER, R



LHC4857  
MB430149  
DELICA DE  
SUSP. BUMPER

# TENSION ROD BUSH

|                                                                                                                                                           |                                                                                                                                                       |                                                                                                                                                         |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC0205<br/>54476-H1001<br/>B210<br/>TENSION ROD BUSH</p>             |  <p>LHC3219<br/>48674-19095<br/>COROLLA 4A<br/>BUSH KIT</p>           |  <p>LHC4154<br/>51380-SE0-000<br/>ACCORD 86-89<br/>TORQUE ROD BUSH</p> |
|  <p>LHC0264<br/>54476-W5000<br/>B310<br/>TENSION ROD BUSH</p>             |  <p>LHC3218<br/>48674-19055<br/>KE30, RT130<br/>STRUT BAR KIT</p>    |  <p>LHC4155<br/>51390-SE0-033<br/>ACCORD 86-89<br/>TORQUE ROD BUSH</p> |
|  <p>LHC1920<br/>55193-50A00-D<br/>B12 85-90<br/>TORQUE ROD BUSH</p>       |  <p>LHC0820<br/>48674-22020<br/>TOYOTA<br/>STRUT BUSH</p>            |  <p>LHC4200<br/>51381-SM4-013<br/>ACCORD '90<br/>TORQUE ROD BUSH</p>   |
|  <p>LHC4216<br/>55148-50A00-D<br/>SUNNY B12 87-91<br/>TORQUE ROD BUSH</p> |  <p>LHC4153<br/>48674-22060<br/>TOYOTA<br/>STRUT BUSH</p>            |  <p>LHC4201<br/>51391-SM4-013<br/>ACCORD 90<br/>TORQUE ROD BUSH</p>    |
|  <p>LHC0393<br/>54477-V1010<br/>180B<br/>TENSION ROD BUSH</p>             |  <p>LHC4153K<br/>48674-29045<br/>HIACE, HILUX<br/>STRUT BUSH KIT</p> |  <p>LHC0980<br/>51398-SM4-000K<br/>ACCORD 90<br/>TORQUE BUSH KIT</p>   |
|  <p>LHC2861<br/>54476-V0100<br/>Y30<br/>TENSION ROD BUSH</p>              |  <p>LHC4033<br/>48674-12030<br/>TOYOTA<br/>STRUT BAR BUSHING</p>     |  <p>LHC0915<br/>MB175617<br/>GALANT '87<br/>STRUT BUSH</p>             |
|  <p>LHC2862<br/>54477-V5001<br/>Y30<br/>TENSION ROD BUSH</p>             |  <p>LHC4032<br/>48674-30040<br/>TOYOTA<br/>STRUT BAR BUSHING</p>    |  <p>LHC0916<br/>MB175618<br/>GALANT '87<br/>STRUT BUSH</p>            |
|  <p>LHC0515<br/>54476-F0200<br/>720<br/>TENSION ROD BUSH</p>            |  <p>LHC4390<br/>45341-85010<br/>SK410<br/>BUSH</p>                 |  <p>LHC0611<br/>MD001765<br/>L300<br/>TENSION ROD BUSH</p>           |
|  <p>LHC4826<br/>54476-01G00K<br/>720<br/>ROD BUSH KIT</p>               |  <p>LHC4346<br/>8-94139-325<br/>I-MARK 85<br/>STRUT BUSH</p>       |  <p>LHC2343<br/>MB001766<br/>MITSUBISHI<br/>STRUT BAR BUSH</p>       |
|  <p>LHC0035<br/>74BB-3470-AA<br/>CORTINA<br/>TIE BAR BUSH</p>           |  <p>LHC4414<br/>8-94433-672<br/>KB46 88-97<br/>TORQUE ROD BUSH</p> |  <p>MB176373-R<br/>PICK UP ALL 87-91<br/>STRUT KIT</p>               |

# **SPRING EYE BUSH**



LHC0285  
55045-G2500  
C20  
SPRING BUSH



LHC0286  
55046-G2500  
C20  
SPRING BUSH, R



LHC0516  
55045-01W10  
720  
SPRING BUSH



LHC0517  
55046-01W10  
720  
SPRING BUSH



LHC2237  
55046-B8460  
E20  
SPRING BUSH



LHC2238  
55046-R8000  
E23  
SPRING BUSH



LHC4122  
55046-01G00  
SD23, TD25  
SPRING BUSH



LHC1184  
MB025153  
FE211  
SPRING BUSH



LHC0585  
MB111071  
L300  
SPRING BUSH



LHC0586  
MB111070  
L300  
SPRING BUSH



LHC0806  
90385-15016  
TOYOTA  
SPRING BUSH



LHC0807  
90385-18046  
TOYOTA  
SPRING BUSH



LHC0814  
90385-18009  
TOYOTA BJ70  
SPRING BUSH



LHC2576  
90385-18008  
TOYOTA 4Y  
SPRING BUSH



LHC2977  
90385-18005  
LY30  
SPRING BUSH



LHC0812  
90389-18002  
TOYOTA  
SPRING BUSH



LHC0753  
90043-85049  
V22  
SPRING BUSH, R



LHC0755  
90043-85048  
V22  
SPRING BUSH, R



LHC0698  
41331-62020  
SUZUKI  
SPRING BUSH



LHC0699  
09305-13002  
SUZUKI  
SPRING BUSH



LHC0175  
0191-28-330  
B1600, E1600  
SPRING BUSH



LHC3230  
UB39-28-333  
COURIER  
SPRING BUSH, UPPER



LHC3626  
S001-28-333  
B1800, B2200  
SPRING BUSH



LHC3640  
S087-28-333  
MAZDA  
SPRING BUSH



LHC0740  
W001-28-330  
MAZDA  
SPRING BUSH



LHC2368  
8-94234-319  
ISUZU KB26  
SPRING BUSH



LHC2369  
8-94213-168  
ISUZU KB26  
SPRING BUSH



LHC3951  
8-94113-323  
NKR, NHR  
SPRING BUSH, F



LHC3605  
8-94118-588  
NPR  
SPRING BUSH




LHC3639  
8-94113-314  
NKR  
SPRING BUSH

# **SPRING & LINK EYE BUSH**

**OVER 100 SIZES**



**LHC2559**  
90389-14007  
HIACE YLNGO  
SPRING BUSH



**LHC0786**  
90389-16002  
TOYOTA BU30  
SPRING BUSH



**LHC0754**  
90043-85046  
V22  
SPRING BUSH,F



**LHC0739**  
0559-34-330  
MAZDA  
SPRING BUSH



**LHC1904**  
8-94130-354  
NPR  
SPRING BUSH,F



**LHC2084**  
5-51351-033/5  
NPR  
SPRING BUSH,R



**LHC4222**  
09319-12032  
SK410,408  
SPRING BUSH



**LHC3809**  
55045-B8460  
E20  
SPRING BUSH



**LHC4163**  
55047-01G00  
NISSAN KA24E  
SPRING BUSH



**LHC4162**  
55045-31G00  
NISSAN KA24E  
SPRING BUSH



**LHC2867**  
55046-V0100  
Y30  
LINK BUSH,UPPER



**LHC3169**  
2H4608  
ROVER  
SPRING BUSH



**LHC4565**  
48702-60031  
LAND C. 91-97  
LINK BUSH,R



**LHC4778**  
48702-60040  
LANDCRUISER 91-97  
LINK BUSH,R



**LHC4513**  
16x40x50  
48706-60030  
LANDCRUISER  
BUSH




**LHC4176**  
48702-22330  
CRESSIDA  
LINK BUSH



**LHC4483**  
48702-22370  
CRESSIDA  
LINK BUSH




**LHC4789**  
48702-30070  
CROWN LS130  
LINK BUSH



**LHC4891**  
IMPREZA 1993-2000  
ARM BUSH



**LHC4867**  
55045-60R00  
NISSAN WAGON  
BUSH



**LHC4611**  
52343-SK7-003  
CIVIC'92  
BUSH,R



**LHC4747**  
ACCORD'98  
LINK BUSH,R



**LHC4748**  
ACCORD'98  
LINK BUSH,R



**LHC4749**  
ACCORD'98  
LINK BUSH,R




**LHC4341**  
46310-60A01A  
VITARA  
LINK,R



**LHC4341**  
09319-12043  
SJ413 89-98  
REAR LINK BUSH



**LHC4790**  
55045-41G00  
PATHFINDER 87-93  
LINK BUSH



**LHC4790**  
55120-41G00  
PATHFINDER 87-93  
LINK,UPPER

# STEERING BUSH

LHC0132



B001-32-111XY  
MAZDA 323 80-89  
STEERING BUSH KIT



B456-32-111X  
323'90  
STEERING GEAR BUSH & SPRING



LHC4715  
45522-17020  
COROLLA AE91  
STERING RACK BUSH



LHC3223-25  
45522-12040  
COROLLA'93  
STEERING BUSH



LHC4804  
48128-35A01  
NISSAN  
STEERING GEAR BUSH



48236-61A00  
NISSAN  
STEERING BUSH



LHC7132  
48128-51S00  
NISSAN B13  
STEERING GEAR BUSH



LHC3223-24  
STEERING BUSH



LHC3223-26  
STEERING BUSH



LHC3223-31  
STEERING BUSH

# STEERING RUBBER

LHC4136



48377-50A00  
SENTRA 83-90  
STEERING RUBBER



LHC4137  
48376-50A00  
SENTRA 83-90  
STEERING RUBBER



LHC4759  
54445-52Y00  
SENTRA'91  
STEERING RUBBER, LH



LHC7113  
54445-W1000  
BLUEBIRD 910  
STEERING RUBBER



LHC7112  
54444-41L01  
SKYLINE  
STEERING RUBBER



LHC7110  
48376-51E00  
STANZA'90  
STEERING RUBBER



LHC7111  
48377-56E00  
STANZA'90  
STERING RUBBER



LHC4923  
45517-10050  
TERCEL  
STEERING RUBBER, LH



LHC4942  
G037-32-124  
626'83  
STEERING RUBBER



LHC4760  
MB288983  
MIRAGE 85  
STEERING RUBBER

# POWER STEERING HOSE

LHC5801



SENTRA B13  
SUNNY 91-95




LHC5802  
NISSAN  
B14 1996



LHC5803  
NISSAN  
PRIMERA



LHC5806  
COROLLA 88-91  
1.6 DX, SR5



LHC5805  
COROLLA 93-97 1.8  
POWER STEERING HOSE




LHC5812  
CAMRY'88 2.0  
POWER STEERING HOSE




LHC5807  
CAMRY'92 4CY  
POWER HOSE



LHC5808  
CAMRY'97 2.2  
POWER STEERING HOSE



MB033517  
POWER STEERING HOSE




MB033518  
POWER STEERING HOSE



## OIL CAP

## OIL HOSE




WHEEL REPAIR KIT  
CALIPER KIT

|                                                                                                                                                |                                                                                                                                                               |                                                                                                                                                         |
|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC0125</b><br>0453-10-250<br>MAZDA 323<br>OIL CAP      | <br><b>LHC2221</b><br>14670-54A01<br>CD17<br>ALTERNATOR HOSE                 | <br><b>LHC1766</b><br>171-698-341<br>VW GOLF<br>WHEEL REPA. KIT       |
| <br><b>LHC0181</b><br>E563-10-250<br>E1600,626<br>OIL CAP      | <br><b>LHC2220</b><br>14665-54A01<br>NISSAN CD17<br>OIL HOSE                 | <br><b>LHC1787</b><br>211-698-301<br>VW KOMB<br>WHEEL REPA. KIT       |
| <br><b>LHC0312</b><br>15255-01M00<br>SENTRA B11<br>OIL CAP     | <br><b>LHC0431</b><br>14670-Y7500<br>SD22<br>OIL HOSE                        | <br><b>LHC2038</b><br>SP 2009-3<br>ROVER<br>WHEEL KIT                 |
| <br><b>LHC0394</b><br>15255-W1100<br>180B<br>OIL CAP           | <br><b>LHC0432</b><br>14665-61504<br>SD22<br>OIL HOSE                        | <br><b>LHC2039</b><br>SP7390<br>ROVER<br>WHEEL KIT                    |
| <br><b>LHC3447</b><br>MB000520<br>GALANT<br>OIL CAP            | <br><b>LHC0526</b><br>14665-16A00<br>NISSAN<br>OIL HOSE                      | <br><b>LHC2002</b><br>8-94208-053<br>CHEV PICK UP<br>WHEEL REPAIR KIT |
| <br><b>LHC2025</b><br>15610-611-810<br>ACCORD<br>OIL CAP       | <br><b>LHC2570</b><br>90923-01053<br>TOYOTA<br>OIL HOSE                      | <br><b>LHC0045</b><br>8-94216-949<br>GEMINI<br>CALIPER KIT            |
| <br><b>LHC2328</b><br>12180-11010<br>TOYOTA<br>OIL CAP       | <br><b>LHC1619</b><br>1190.16<br>PEUGEOT<br>OIL HOSE W/CAP                  | <br><b>LHC2370</b><br>8-94216-949<br>GEMINI<br>CALIPER KIT          |
| <br><b>LHC1893</b><br>RENAULT<br>OIL CAP                     | <br><b>LHC1121</b><br>5-13311-910<br>C250,KS<br>OIL HOSE, IN               | <br><b>LHC0311</b><br>41120-01A25<br>SENTRA B11<br>CALIPER KIT      |
| <br><b>LHC2021</b><br>PEUGEOT<br>OIL CAP                     | <br><b>LHC2059</b><br>12x280<br>5-11369-039<br>ISUZU C250<br>OIL HOSE, OUT | <br><b>LHC0436</b><br>SD22<br>CALIPER KIT                           |
| <br><b>LHC2371</b><br>8-94109-791<br>ISUZU GEMINI<br>OIL CAP | <br><b>LHC1876</b><br>MB112269<br>MITSUBISHI<br>OIL HOSE                   | <br><b>LHC3428</b><br>B092-33-24Z<br>MAZDA 323'86<br>CALIPER KIT     |

# STABILIZER BUSH

|                                                                                    |                                                           |                                                                                     |                                                          |                                                                                      |                                                          |
|------------------------------------------------------------------------------------|-----------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------|--------------------------------------------------------------------------------------|----------------------------------------------------------|
|    | LHC4268<br>48815-12180<br>COROLLA '88<br>STABILIZER BUSH  |    | LHC4417<br>54613-88G00<br>D21 '90 4WD<br>STABILIZER BUSH |     | LHC1919<br>83BB-5484-CG<br>SIERRA<br>STABILIZER BUSH     |
|    | LHC4277<br>48815-16140<br>COROLLA AE92<br>STABILIZER BUSH |    | LHC4417<br>54613-32G00<br>D21 '86-89<br>STABILIZER BUSH  |    | NAM4081<br>ROVER METRO 85<br>STABILIZER BUSH             |
|    | LHC4508<br>48818-12080<br>EE90 '88-91<br>STAB.BUSH,R      |    | LHC3465<br>54613-D4400<br>BLUEBIRD<br>STABILIZER BUSH    |     | LHC3501<br>113-411-313<br>V.V. BEETLE<br>STABILIZER BUSH |
|    | LHC4344<br>48815-12220<br>COROLLA '93<br>STAB.BUSH        |    | LHC4272<br>G030-34-1568<br>626 '88-83<br>STAB.BUSH,F     |     | LHC3467<br>0350112<br>OPEL 84-94<br>STABILIZER BUSH      |
|    | LHC4343<br>48818-12150<br>COROLLA 92-95<br>STAB.BUSH      |    | LHC4273<br>G030-28-156<br>626 83-88<br>STABILIZER BUSH   |     | LHC1916-21<br>7700763934<br>R9<br>STABILIZER BUSH        |
|    | LHC0885<br>48815-87703<br>CHARADE<br>STABILIZER BUSH      |    | LHC3859<br>S083-34-156<br>B2200<br>STABILIZER BUSH       |    | LHC3439<br>7700789412<br>R9,R19<br>STAB.BUSH             |
|   | LHC4026<br>48815-87708<br>CHARADE 16V<br>STABILIZER BUSH  |  | LHC4129<br>U871-34-156<br>COURIER F8<br>STABILIZER BUSH  |   | LHC1915<br>7700760264<br>R9<br>STABILIZER BUSH           |
|  | LHC4347<br>MB303052<br>MITSUBISHI<br>BUSH ANTI BAR        |  | LHC4426<br>52315-SB0-000<br>CIVIC 85-92<br>STAB.BUSH     |   | LHC3872<br>7700771562<br>R21<br>STABILIZER BUSH          |
|  | MB573054<br>MB573207<br>MB573385<br>STABILIZER BUSH       |  | LHC2635<br>51316-SH3-000<br>HONDA 16V<br>STABILIZER BUSH |   | LHC3283<br>5094.02<br>PEUGEOT<br>BUSH                    |
|  | LHC4123<br>MB175581<br>L300<br>STABILIZER BUSH            |  | LHC4427<br>8-94318-777<br>ISUZU 4WD<br>STABILIZER BUSH   |  | LHC1610<br>5094.09<br>PEUGEOT 504<br>BUSH                |




# STABILIZER KIT

|                                                                                                                                                   |                                                                                                                                                                                  |                                                                                                                                                      |
|---------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC0252</b><br>54618-H2300<br>B210<br>STABILIZER KIT       | <br><b>LHC4233</b><br>MB241974<br>MIRAGE, EXCELL<br>STABILIZER KIT                              | <br><b>LHC1732</b><br>GM<br>STABILIZER KIT                         |
| <br><b>LHC3499</b><br>54618-01A00<br>SENTRA B11<br>STABILIZER KIT | <br><b>LHC2650</b><br>MB527385<br>DELICA 2.5 2WD<br>STABILIZER KIT                              | <br><b>LHC6763</b><br>NEON<br>STAB. KIT, F                         |
| <br><b>LHC3625</b><br>54618-47B01K<br>MARCH<br>STABILIZER KIT     | <br><b>MB527168</b><br>MONTERO 87-91<br>STAB. BUSH KIT                                          | <br><b>LHC3527</b><br>S/B-8-93-195-1<br>OPEL<br>STABILIZER BAR     |
| <br><b>LHC2545</b><br>54618-01G00<br>D21<br>STAB. KIT             | <br><b>LHC4579</b><br>L200 84-91<br>MB185476<br>STABILIZER KIT                                  | <br><b>LHC3528</b><br>S/B-8-75-170-1<br>OPEL<br>STABILIZER BAR     |
| <br><b>LHC0124</b><br>B029-34-158K<br>323 '80<br>STAB. KIT        | <br><b>MB527385</b><br>DELICA 2.5 2WD<br>STAB. BUSH                                             | <br><b>LHC3529</b><br>S/B-8-58-170-1<br>OPEL '86<br>STABILIZER BAR |
| <br><b>LHC0149</b><br>MAZDA 323 '86<br>STABILIZER KIT             | <br><b>51313-SD5-000K</b><br>CIVIC 88-95<br>ACCORD 86-89<br>STABILIZER KIT, F                   | <br><b>LHC6721</b><br>350261<br>ASTRA '88 1.6<br>LINK KIT          |
| <br><b>LHC6768</b><br>929, MPV 86-96<br>STAB. KIT               | <br><b>51313-SB2-000K</b><br>CIVIC 80-87<br>ACCORD 78-85<br>STABILIZER KIT, F                 | <br><b>LHC6721-22</b><br>350260<br>OPEL ASTRA 2.0<br>LINK KIT     |
| <br><b>LHC3039</b><br>626 83-86<br>STABILIZER KIT               | <br><b>LHC4549K</b><br>ORIGINAL TYPE 13 PCS<br>51313-SM4-000K<br>ACCORD '90<br>STABILIZER KIT | <br><b>LHC6718</b><br>191-411-315<br>GOLF, JETTA '92<br>STAB. KIT |
| <br><b>LHC6767</b><br>8AC2-34-100<br>626 87-92<br>STAB. KIT     | <br><b>LHC2647</b><br>8AB1-34-100<br>323 86-89<br>STABILIZER KIT                              | <br><b>LHC6746</b><br>3530230<br>VOLVO 240 84-92<br>STAB. KIT    |
| <br><b>LHC4179K</b><br>FORD<br>STABILIZER KIT                   | <br><b>LHC2648</b><br>8AB2-34-100<br>323 90-94<br>STAB. KIT                                   | <br><b>LHC3262</b><br>7701453465<br>R12.18<br>STABILIZER KIT     |



# STABILIZER LINK

|                                                                                    |                                                                 |                                                                                     |                                                                    |                                                                                      |                                                               |
|------------------------------------------------------------------------------------|-----------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------|
|     | LHC0976-11<br>1661237<br>FORD FIESTA'90<br>STAB. KIT            |    | LHC6715-24<br>24mm<br>357-411-315D<br>VW PASSAT<br>STABILIZER LINK |    | LHC6717<br>535-411-315<br>GOLF, JETTA'92<br>STABILIZER KIT    |
|    | LHC6728<br>93BB-3B438-CA<br>MONDEO<br>STAB. KIT                 |    | LHC6714<br>T4 2.0/2.5 GAS<br>STABILIZER ROD, F                     |    | LHC6701<br>31351091764<br>BMW 316/325 82-91<br>STAB. LINK     |
|    | LHC6729<br>93BB-5K566-AC<br>MONDEO'93<br>LINK, R                |    | LHC6716<br>T4 2.4 DIESEL<br>STABILIZER ROD, F                      |    | LHC6702<br>31351134582<br>BMW E28, E34/518 82-91<br>STAB. KIT |
|    | LHC6730<br>93BB-5K566-AF<br>MONDEO'97<br>LINK, R                |    | LHC6710<br>4A0-505-389<br>AUDI 100 A4 90-94<br>STAB. LINK          |    | LHC6703<br>31351091496<br>BMW 728 E38 94<br>STAB. KIT, F      |
|    | LHC6749<br>3467714<br>VOLVO 440/480 88-91<br>STABILIZER KIT, RH |    | LHC6711<br>4D0-505-548C<br>AUDI'94 A8<br>BAR LINK, F RH            |    | LHC6704<br>33551091497<br>728 E38 94<br>STAB. LINK, R         |
|    | LHC6750<br>3467713<br>VOLVO 440/480 88-91<br>STABILIZER KIT, LH |    | LHC6712<br>4D0-505-465D<br>AUDI'94 A8<br>STABILIZER KIT            |    | LHC6706<br>31351091856<br>BMW 528 E39 95<br>STAB. KIT, F RH   |
|   | LHC6751<br>1387860<br>VOLVO 850'92<br>STABILIZER KIT, F         |   | LHC6725<br>5087.23<br>205, 309<br>CONNECTION ROD                   |  | LHC6705<br>31351091855<br>BMW 528 E39 95<br>STAB. KIT, F LH   |
|  | LHC6752<br>3530304<br>VOLVO 960 '94<br>LINK, R                  |  | LHC6726<br>5087.21<br>305<br>CONNECTION ROD                        |  | LHC6707<br>33551135307<br>BMW 316 '90<br>REAR BAR LINK        |
|  | LHC6753<br>6819253<br>VOLVO 960'94<br>STAB. KIT, F              |  | LHC6727<br>5087.27<br>405, 1.6<br>CONNECTION ROD                   |  | LHC6708<br>33551126932<br>BMW 316 82-89<br>REAR BAR LINK      |
|  | LHC6740<br>140-320-1289<br>W140'91<br>LINK KIT, F RH            |  | LHC6741<br>140-320-1189<br>W140'91<br>STAB. KIT                    |  | LHC6709<br>33321126476<br>BMW 5S. 88-95<br>REAR BAR LINK      |

# STRUT MOUNT

|                                                                                    |                                                      |                                                                                     |                                                                   |                                                                                      |                                                                 |
|------------------------------------------------------------------------------------|------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------|--------------------------------------------------------------------------------------|-----------------------------------------------------------------|
|    | LHC0105<br>B001-34-390<br>MAZDA 323<br>STRUT MOUNT,F |    | LHC3750<br>48609-12192<br>COROLLA '88<br>STRUT MOUNT,F            |    | LHC3091<br>171-412-329<br>V.W. '74-82<br>STRUT MOUNT,F          |
|    | LHC0106<br>B001-28-390<br>MAZDA 323<br>STRUT MOUNT,R |    | LHC3751<br>LHC4109<br>48750-12080<br>COROLLA '88<br>STRUT MOUNT,R |    | LHC3123<br>191-412-329<br>V.V. '83<br>STRUT MOUNT,F             |
|    | LHC3032<br>B455-34-390<br>323 '90<br>STRUT MOUNT,F   |    | LHC4260<br>48609-33011<br>CAMRY '93<br>STRUT MOUNT,F              |     | LHC4295<br>31331124508<br>BMW 520 E30 '85<br>STRUT MOUNT        |
|    | LHC3341<br>B455-28-390D<br>323 '90<br>STRUT MOUNT,R  |    | LHC3752<br>48609-16040<br>TERCEL '83<br>STRUT MOUNT               |    | LHC4296<br>B/3.8x93(112)x54<br>BMW<br>STRUT MOUNT               |
|    | LHC0170<br>G030-34-390<br>MAZDA 626<br>STRUT MOUNT,F |    | LHC4291<br>48750-16040<br>TERCEL<br>STRUT MOUNT,R                 |    | LHC4292<br>B/3.8x123(85)x42<br>VOLVO 240,244,264<br>STRUT MOUNT |
|    | LHC2375<br>G030-28-390<br>MAZDA 626<br>STRUT MOUNT   |    | LHC3981<br>48609-16090<br>TERCEL 87-90<br>STRUT MOUNT             |    | LHC4286<br>10x155x46<br>VOLVO 240<br>STRUT MOUNT                |
|   | LHC1877<br>GJ23-34-380B<br>626 '88<br>STRUT MOUNT,F  |   | LHC4134<br>48609-16160<br>TERCEL 91-93<br>STRUT MOUNT             |   | LHC2894<br>5165.25<br>PEUGEOT 305<br>STRUT MOUNT,R              |
|  | LHC1878<br>GJ21-28-380<br>626 '88<br>STRUT MOUNT,R   |  | LHC2958<br>48609-87704<br>CHARADE G11<br>STRUT MOUNT              |  | LHC1615<br>5210.13<br>504<br>ABSORBER SUPPORT                   |
|  | LHC4262<br>LA01-34-380<br>929<br>STRUT MOUNT         |  | LHC3837<br>48609-87712<br>DAIHATSU G100<br>STRUT MOUNT,F          |  | LHC3268<br>5210.14<br>404<br>STRUT MOUNT                        |
|  | LHC4309<br>GN82-34-380<br>MX6 '88<br>STRUT MOUNT     |  | LHC0714<br>41710-79021<br>SUZUKI<br>STRUT MOUNT                   |  | LHC3276<br>5210.17<br>PEUGEOT 504<br>ABSORBER MOUNT             |

# SHOCK ABSORBER PARTS

|                                                                                                                                                  |                                                                                                                                                    |                                                                                                                                                      |
|--------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC0114</b><br>B001-34-111<br>MAZDA 323<br>STRUT BOOT, F  | <br><b>LHC2156</b><br>55241-50A01<br>SENTRA<br>STRUT BOOT, R      | <br><b>LHC0852</b><br>11.5x22x13<br>UNIVERSAL<br>ABSORBER BUSH      |
| <br><b>LHC0115</b><br>B001-28-111A<br>MAZDA 323<br>STRUT BOOT, R | <br><b>LHC2203</b><br>54052-52A00<br>SENTRA E16<br>STRUT BUMPER   | <br><b>LHC0280</b><br>15x30x18.5<br>UNIVERSAL<br>ABSORBER GROMMET   |
| <br><b>LHC4728</b><br>B455-34-111<br>323'90<br>STRUT COVER       | <br><b>LHC2204</b><br>54320-50A00<br>SENTRA<br>STRUT INSULATOR    | <br><b>LHC3139</b><br>12x30x18<br>UNIVERSAL<br>ABSORBER BUSH        |
| <br><b>LHC4729</b><br>B455-28-111A<br>323'90<br>STRUT BOOT       | <br><b>LHC2205</b><br>54055-01E00<br>SENTRA E16<br>STRUT BOOT, F  | <br><b>LHC3500</b><br>18.8x37x22<br>UNIVERSAL<br>ABSORBER BUSH      |
| <br><b>LHC0155</b><br>G030-34-015<br>MAZDA 626<br>STRUT BOOT, F  | <br><b>LHC3031</b><br>54050-02E00<br>BLUEBIRD<br>STRUT BUMPER     | <br><b>LHC1459</b><br>56129-90000<br>RD8<br>ABSORBER BUSH           |
| <br><b>LHC0156</b><br>G030-28-015A<br>MAZDA 626<br>STRUT BOOT, R | <br><b>LHC2634</b><br>48331-87702<br>CHARADE 83-93<br>STRUT BOOT | <br><b>LHC0820</b><br>48674-22020<br>TOYOTA<br>STRUT BUSH           |
| <br><b>LHC0157</b><br>G030-34-111<br>626<br>STRUT BUMPER, F    | <br><b>LHC4730</b><br>MD001-34-111<br>FESTIVE'86<br>STRUT COVER | <br><b>LHC0042</b><br>71BB-18016-8A<br>CORTINA<br>ABSORBER BUSH   |
| <br><b>LHC0158</b><br>G030-28-111<br>626<br>STRUT BUMPER, R    | <br><b>LHC4731</b><br>MD001-28-111<br>FESTIVE'86<br>STRUT COVER | <br><b>LHC0614</b><br>8x22.5x14<br>UNIVERSAL<br>ABSORBER BUSH     |
| <br><b>LHC3059</b><br>GJ21-34-111<br>626'88<br>STRUT BUMPER, F  | <br><b>LHC3062</b><br>GJ21-28-111<br>626'88<br>STRUT BUMPER, R  | <br><b>LHC0210</b><br>10x25.4x16<br>UNIVERSAL<br>ABSORBER GROMMET |
| <br><b>LHC3060</b><br>GJ21-34-015<br>626'88<br>STRUT BOOT, F   | <br><b>LHC3061</b><br>GJ21-28-015<br>626'88<br>STRUT BOOT, R    | <br><b>LHC0290</b><br>9x29x16<br>UNIVERSAL<br>ABSORBER GROMMET    |

# CENTER CUSHION



LHC2222

37521-V1625  
NISSAN  
CUSHION, ASSY



LHC0519

37521-01V25-B  
720  
CENTRE BEARING



LHC3918

37521-01V25-S  
720  
CENTRE BEARING



LHC3921

37521-32G25  
720 D21 4WD  
CUSHION, ASSY



LHC4818

37521-J2100  
Q140  
RUBBER+BEARING



LHC3149A

0755-25-300A  
BN61, FAMILIA  
CUSHION, ASSY



LHC4815A

P030-25-310A  
E2200, B2200 '90  
CUSHION & BEARING



LHC0742A

W001-25-310  
T4100  
CUSHION ASSY



LHC3804

MB154080  
GALANT 79-87  
CUSHION, ASSY



LHC3146

MB000083  
CANTER FE  
CUSHION, ASSY



LHC2564

37230-30030  
CROWN 80-82  
CUSHION, ASSY



LHC2563

37230-30010  
TOYOTA  
CUSHION, ASSY



LHC3147-21

37230-30021  
CROWN '75  
CUSHION



LHC2563-21

37230-30052  
CROWN '88 MS123  
CUSHION ASSY



LHC0789

37230-36H00  
TOYOTA  
CUSHION ASSY



LHC0801

37230-36070  
TOYOTA 13V  
CUSHION ASSY



LHC3150

37230-35050  
YK, LN 55, 85  
CUSHION, ASSY



LHC3357

37230-35080  
HILUX YN65, LN65  
CUSHION



LHC3923

37230-36080  
COASTER RB20, HB31  
CUSHION ASSY



LHC0759

37208-87302  
V22  
CUSHION, ASSY



LHC4274

8-94222-972  
ISUZU  
CUSHION ASSY



8-94328-799  
ISUZU 91 4WD  
CUSHION ASSY



8-94328-800  
ISUZU 91 2WD  
CUSHION ASSY



LHC1128

5-37516-006  
KT, NPR  
CUSHION, ASSY



LHC1115

5-37516-005  
KS22, NKR  
CUSHION, ASSY



LHC6769

1-37510-088  
FTR, JCR  
CUSHION ASSY



LHC2639

26111206502  
BMW E21  
CUSHION & BEARING



LHC6733

26121226723  
BMW E32  
CUSHION, ASSY



LHC6734

26121225152  
BMW E30 1987  
CENTER BEARING




LHC2145

123 410 1081  
BENZ  
CENTER RUBBER


RADIATOR DRAIN COCK  
WATER PUMP PLUG

PEDAL PAD


AIR CLEANER HOSE

|                                                                                    |                                                                        |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------|
|    | LHC0250<br>21480-18000<br>SUNNY<br>DRAIN COCK                          |
|    | LHC0358<br>21440-D0100<br>STANZA, SUBARU<br>DRAIN COCK                 |
|    | LHC1873<br>21440-01E00<br>B12<br>DRAIN COCK                            |
|    | LHC2352<br>MITSUBISHI<br>MAZDA, TOYOTA<br>DRAIN COCK                   |
|    | LHC0636<br>16185-87201<br>16185-87701<br>MAZDA, DAIHATSU<br>DRAIN COCK |
|    | LHC0799<br>90910-09054<br>TOYOTA<br>DRAIN COCK                         |
|   | LHC2899<br>23322-54010<br>TOYOTA<br>DRAIN COCK                         |
|  | LHC0116<br>3/8"<br>MAZDA 323<br>WATER PUMP PLUG                        |
|  | LHC0713<br>1/2"<br>17467-63200<br>SUZUKI<br>WATER PUMP PLUG            |
|  | LHC0217<br>5/8"<br>SUNNY<br>WATER PUMP PLUG                            |


|                                                                                     |                                                       |
|-------------------------------------------------------------------------------------|-------------------------------------------------------|
|    | LHC0129<br>0225-43-028<br>MAZDA 323<br>PEDAL PAD      |
|    | LHC0219<br>46531-18001<br>SUNNY<br>PEDAL PAD          |
|    | LHC2018<br>48520-579-000<br>HONDA ACCORD<br>PEDAL PAD |
|    | LHC0784<br>31321-36010<br>TOYOTA<br>PEDAL PAD         |
|    | LHC2317<br>31321-14020<br>TOYOTA<br>PEDAL PAD         |
|    | LHC0649<br>MB126093<br>MITSUBISHI<br>PEDAL PAD        |
|   | LHC1934<br>76x62x15<br>185054<br>ROVER<br>PEDAL PAD   |
|  | LHC1935<br>94x67x15<br>1185387<br>ROVER<br>PEDAL PAD  |
|  | LHC1932<br>JHM49<br>ROVER<br>PEDAL PAD, BRAKE         |
|  | LHC3113<br>JHM50<br>ROVER<br>PEDAL PAD                |

|                                                                                      |                                                               |
|--------------------------------------------------------------------------------------|---------------------------------------------------------------|
|    | LHC0564<br>16577-T6210<br>SD22<br>AIR CLEANER HOSE            |
|    | LHC0577<br>16572-T8000<br>Z20<br>AIR CLEANER HOSE             |
|    | LHC0871<br>17242-PB9-621<br>CIVIC<br>AIR CLEANER HOSE         |
|    | LHC1638<br>PEUGEOT 305<br>AIR CLEANER HOSE                    |
|     | LHC2560<br>17881-56040<br>TOYOTA<br>BU30 AIR HOSE             |
|    | LHC2561<br>17881-48505<br>TOYOTA BU30<br>AIR HOSE             |
|   | LHC1903<br>31x68x320<br>17881-78020<br>TOYOTA 6.9<br>AIR HOSE |
|  | LHC1168<br>MC431157<br>FM<br>AIR CLEANER HOSE                 |
|  | LHC1166<br>3.2"x4"x28"<br>MC402880<br>FM 6D14<br>AIR HOSE     |
|  | LHC1378<br>4.6"x5.6"x28"<br>9002-33468A<br>SH<br>AIR HOSE     |


# DOOR WEATHER STRIP




LHCW0011  
CAR DOOR SPONGE




LHCW0012  
CAR DOOR SPONGE




LHCW0013  
CAR DOOR SPONGE




LHCW0014  
CAR DOOR SPONGE




LHCW0015  
CAR DOOR SPONGE




LHCW0016  
CAR DOOR SPONGE



LHCW0017  
CAR DOOR SPONGE




LHCW0018  
CAR DOOR SPONGE



LHCW0019  
CAR DOOR SPONGE



LHCW0041  
TRUNK WEATHER STRIP



LHCW0042  
TRUNK WEATHER STRIP



LHCW0051  
DOOR WEATHER STRIP



LHCW0052  
DOOR WEATHER STRIP



LHCW0053  
DOOR WEATHER STRIP



LHCW0054  
DOOR WEATHER STRIP

# SPORT CARS

## HARD RACE RUBBER

### PRELUDE 92-96



50814-SS0-000S  
PRELUDE 92-96 2.2  
ENGINE MOUNT



50820-SS0-J01S  
PRELUDE 92-96  
ENGINE MOUNT



50806-SS0-000S MT




50806-SS0-982S AT



50810-SS0-000S  
PRELUDE 92-96  
ENGINE MOUNT

### FRONT SUSPENSION




51306-SS0-010S

51320-SS0-003S

51314-SM4-020S

### REAR SUSPENSION




52315-SS0-010S

52316-SP0-000S

52320-SS0-003S




52357-SS0-013S



52622-SS0-010S


52354-SS0-023S

52353-SM4-962S



51393-SL5-013S

51810-SS0-003S



51391-SS0-013S

51381-SS0-013S


### INTEGRA 94-00

#### ENGINE MOUNT



50800-XH4-S1N0  
5PCS

### FRONT SUSPENSION



51631-XE5-S0N0  
8PCS

51455-XG5-S0N0  
4PCS


51391-XG5-S0N0  
2PCS

51306-XH4-BUSH  
2PCS

51392-XG5-S0N0  
2PCS

51810-XE5-S0N0  
2PCS

### REAR SUSPENSION



52393-XE9-S0N0  
2PCS

52395-XE5-S0N0  
2PCS

52365-XE5-S0N0  
4PCS

52315-XE5-BUSH  
2PCS

52622-XH3-S0N0  
2PCS

52343-XE5-S0N0  
4PCS

52385-XE9-S0N0  
2PCS

# ENGINE & GEAR BOX MOUNTING

**NISSAN**

Replace parts

**NISSAN**

Replace parts

**NISSAN**

Replace parts

LHC4742



NISSAN '95 ADWAGON  
ENGINE MOUNT

LHC4699



11210-40F00  
240SX 89-94  
ENGINE MOUNT, RH

LHC3553



11350-50Y00  
SENTRA B13 '90  
BUFFER



11220-40F00  
240SX 89-93  
D21 '92  
ENGINE MOUNT, LH



11320-35F00  
240SX 89-93  
ENGINE MOUNT, R

LHC3789



11210-50Y00  
B13 SENTRA '90  
ENGINE MOUNT, RH

LHC4603



11270-2B010  
ALTIMA 93 2.4 AT  
ENGINE MOUNT, F



LHC4605  
11210-1E813  
ALTIMA 93-97 2.4 AT  
ENGINE MOUNT, RH

LHC3791



11220-50Y05  
B13 1.4 MTM '90  
ENG. MOUNT, LH

LHC4606



11220-1E810  
ALTIMA 93 2.4 AT  
ENGINE MOUNT, LH



LHC4604  
11320-2B010  
ALTIMA 93 2.4 AT  
ENGINE MOUNT, R

LHC3790



11320-50Y10  
B13 1.6 ATM '90  
ENGINE MOUNT, R

LHC4435



11271-50J01  
PRIMERA  
ENGINE INSULATOR



LHC4434  
11210-62J00  
PRIMERA  
ENGINE MOUNT, RH

LHC3953



11220-50Y10  
B13 91-94 ATM  
ENGINE MOUNT, LH

LHC4433



11220-62J22  
PRIMERA ATM  
ENGINE MOUNT, LH



LHC4434-21  
11210-64J06  
PRIMERA  
ENG. MOUNT, RH

LHC3954



11220-50Y00  
B13 91-94 MTM  
ENGINE MOUNT, LH

LHC7058



11220-62J02  
PRIMERA MTM  
ENGINE MOUNT, LH



LHC4243  
11320-64J00  
PRIMERA  
ENGINE MOUNT, R

LHC3928



11320-50Y00  
B13 91-94 MTM  
MOUNT, REAR

LHC3737



11220-54A00  
CD17 DIESEL  
ENGINE MOUNT, LH




LHC4355  
11210-50Y00  
CD17, B13 92-95  
ENG. MOUNT

LHC3897



11220-11N00  
E24 VAN 88-94  
ENGINE MOUNT, F

LHC3728



11320-50A04  
NISSAN CD17  
ENGINE MOUNT, R




LHC4429  
11210-0W800  
SENTRA 91-94 2.0  
ENG. MOUNT, RH

LHC3217



11320-40N00  
E24 VAN 88-94  
ENGINE MOUNT, R

LHC3773



11220-02B02  
MARCH MA10  
ENGINE MOUNT



LHC4141  
11220-50A11  
B12 89-90 ATM  
MOUNT, LH

LHC4170




11320-01G00  
DATSUN 720, TD25  
ENGINE MOUNT, R

# ENGINE & GEAR BOX MOUNTING

**TOYOTA** Replace parts

**TOYOTA** Replace parts

**TOYOTA** Replace parts



LHC4225  
12363-74120  
CAMRY 4CY 92-93  
BUFFER



LHC4224  
12363-62020  
CAMRY 6CY 92-93  
BUFFER



LHC3724  
12361-16040  
COROLLA EE90, GEO  
ENGINE MOUNT, F



LHC4547  
12361-74252  
CAMRY 2.2 92-96 AT  
ENGINE MOUNT, F



LHC4548  
12371-74312  
CAMRY 92 2.2 AT  
ENGINE MOUNT, R



LHC4712  
12362-74110  
CAMRY '90 2.0 SV30  
ENGINE MOUNT, RH



LHC4830  
12361-74241  
CAMRY 2.2 92-96 MT  
ENG. MOUNT, F



LHC4831  
12371-74301  
CAMRY 2.2 92-96 MT  
ENGINE MOUNT, R



LHC3822  
12371-74150  
CAMRY EE90 88-92  
ENG. MOUNT, R



LHC4840  
12360-62010  
LEXUS, CAMRY 3.0 92 AT  
ENGINE MOUNT



LHC4462  
12371-62060  
CAMRY, AVALON V6 95 AT  
ENGINE MOUNT



LHC4178  
12363-15020  
COROLLA 88-92  
ENGINE MOUNT




LHC4685  
12361-74210  
CAMRY SV30 90-94 AT  
ENGINE MOUNT, F




LHC4684  
12371-64190  
CAMRY SV30 90-94  
ENGINE MOUNT, R



LHC3722  
12361-74030  
2.0 MTW '88  
ENGINE MOUNT, F



LHC4468  
12372-74380  
CAMRY 2.2 92-96 AT  
ENGINE MOUNT, R



LHC4471  
12372-62080  
CAMRY '95 V6 AT  
ENGINE MOUNT, R



LHC3723  
12361-74060  
2.0 ATM '88  
ENGINE MOUNT, F



LHC7085  
COROLLA 2C CE100  
1992  
ENGINE MOUNT, F



LHC7083  
COROLLA 2C CE100  
1992  
ENG. MOUNT, RH



LHC4168  
12371-15230  
GEO, COROLLA '92  
ENGINE MOUNT AT




LHC7086  
COROLLA CE100 2C  
1992  
ENGINE MOUNT, R



LHC7084  
COROLLA CE100 DIESEL  
1992  
ENGINE MOUNT, R



LHC4093  
12371-15200  
COROLLA 88-92  
ENGINE MOUNT MT



LHC3963  
12362-15001  
AE80 84-86  
ENGINE MOUNT, F



LHC4187  
12372-15061  
AE80, EE80 85-88  
ENGINE MOUNT



LHC3819  
12371-64100  
CAMRY '89  
ENGINE MOUNT, R



LHC4121  
12371-15121  
AE80 EE80 AT 85-88  
ENG. MOUNT, REAR



LHC4186  
12372-15110  
COROLLA 88-91  
ENGINE MOUNT



LHC3206  
12371-16280  
COROLLA '93  
ENGINE MOUNT

# ENGINE & GEAR BOX MOUNTING

**MAZDA** Replace parts

**MAZDA** Replace parts

**MAZDA** Replace parts

|                                                                                                                                                               |                                                                                                                                                             |                                                                                                                                                            |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC4689</b><br>GA2A-39-070<br>626'92 MT<br>ENG. MOUNT                  | <br><b>LHC3947</b><br>GA2A-39-050<br>MAZDA 626'92<br>ENGINE MOUNT, F       | <br><b>LHC4197</b><br>GA2A-39-060<br>626'92 HX6<br>ENG. MOUNT, RH        |
| <br><b>LHC4690</b><br>GA2C-39-070<br>626'92 AT<br>ENG. MOUNT                  | <br><b>LHC4404</b><br>GA2A-39-040<br>626'93 MTH<br>ENGINE MOUNT            | <br><b>LHC4214</b><br>GA2G-39-100<br>626'93<br>ENG. MOUNT                |
| <br><b>LHC4641</b><br>KB31-39-070<br>626'95<br>ENG. MOUNT                     | <br><b>LHC4338</b><br>GA2C-39-040<br>626'93 ATM<br>ENGINE MOUNT            | <br><b>LHC4215</b><br>GA2E-39-100<br>626'93<br>MOUNT, CENTER             |
| <br><b>LHC0104</b><br>B001-39-060<br>MAZDA 323<br>ENGINE MOUNT                | <br><b>LHC4737</b><br>KB31-39-040<br>626'94 AT 4CY<br>ENGINE MOUNT         | <br><b>LHC2617</b><br>GJ21-39-070<br>626 MTH 88-91<br>ENGINE MOUNT, R    |
| <br><b>LHC4679</b><br>BC1F-39-060<br>LIATA, AZTEC '95<br>ENGINE MOUNT         | <br><b>LHC4275</b><br>BC1D-39-04XB<br>LIATA, AZTEC '95<br>ENGINE MOUNT     | <br><b>LHC4193</b><br>GJ23-39-070<br>626 88-92 ATM<br>ENGINE MOUNT       |
| <br><b>LHC4276</b><br>BC1D-39-050A<br>LIATA, AZTEC '95 MT<br>ENGINE MOUNT, F | <br><b>LHC4329</b><br>BC1E-39-100<br>LIATA, AZTEC '95<br>ENGINE MOUNT     | <br><b>LHC4192</b><br>GJ23-39-040<br>626'88 INJ.<br>MOUNT, REAR         |
| <br><b>LHC4328</b><br>BG1D-39-050<br>LIATA, AZTEC '95 AT<br>ENGINE MOUNT    | <br><b>LHC4775</b><br>BC1D-39-100<br>PROTEGE '95 MT<br>ENGINE MOUNT ASSY | <br><b>LHC3898</b><br>GJ23-39-050<br>626'88 ATM<br>ENG. MOUNT, F        |
| <br><b>LHC0148</b><br>B092-39-040<br>323'88<br>ENGINE MOUNT, R              | <br><b>LHC4104</b><br>91NX-39-050<br>323 89-93<br>ENG. MOUNT, F          | <br><b>LHC3215</b><br>GM02-39-040<br>626 88-92 ATM<br>ENG. MOUNT, REAR |
| <br><b>LHC4024</b><br>B455-39-050<br>MAZDA 323'90<br>ENG. MOUNT, F          | <br><b>LHC4094</b><br>B182-39-060<br>MAZDA 89-93 ATM<br>ENGINE MOUNT     | <br><b>LHC2180</b><br>G032-39-060<br>626 83-87 ATM<br>ENG. MOUNT, F    |
| <br><b>LHC3900</b><br>BR74-39-040<br>323'90<br>ENGINE MOUNT, R              | <br><b>LHC4198</b><br>BR70-39-060<br>323'90 1.6<br>ENGINE MOUNT          | <br><b>EA03-39-060</b><br>MX3 90-93 V6<br>ENGINE MOUNT                 |

# HONDA Replace parts CIVIC, ACCORD



LHC4241

50810-SE0-J31  
ACCORD 88-90  
ENGINE MOUNT, F



LHC4744

50810-SV4-J81  
ACCORD 95 AT  
ENGINE MOUNT



LHC4054  
50841-SR3-030  
50841-SR3-983  
CIVIC '92  
ENGINE MOUNT, RH



LHC4458

50806-SV4-000  
ACCORD '95 2.2 MT  
ENGINE MOUNT, RH



LHC4621

50810-SV4-000  
ACCORD 96 2.2L  
ENGINE MOUNT



LHC3869

50842-SR3-030  
CIVIC '92  
ENG. MOUNT, LH



LHC4360

50840-SV4-980  
ACCORD 95 ATM  
ENGINE MOUNT, F



LHC4459

50820-SV4-J01  
ACCORD 95 2.2  
ENGINE MOUNT



LHC3777

50820-SR3-J02  
CIVIC '92



LHC4733

50814-SF1-980  
PRELUDE '88  
ENGINE MOUNT



LHC4709

50815-SF1-980  
PRELUDE 88-91 2.0 AT  
ENGINE MOUNT



LHC3927

50810-SR3-010  
CIVIC '92 ALL



LHC7056

50820-SF1-000  
PRELUDE 2.0 88-91  
ENGINE MOUNT



LHC4898

50810-SF1-980  
PRELUDE 89-91 2.0 AT  
ENGINE MOUNT



LHC4235

50805-SR3-010  
CIVIC '92 MTW  
ENGINE MOUNT, RH



LHC0859

50830-SA0-020  
CIVIC  
TORQUE ROD



LHC3774

50805-SH3-020  
CIVIC '88 16V MTW  
ENGINE MOUNT



LHC4238

50820-SR3-J11  
CIVIC '94 ABS  
ENGINE MOUNT, LH



LHC4180

50821-SE0-050  
ACCORD 86-89  
ENGINE MOUNT



LHC3775

50805-SH3-983  
CIVIC '88 16V ATM  
ENGINE MOUNT



LHC4237

50805-SR3-951  
CIVIC '92 ATM  
ENGINE MOUNT, RH



LHC0952

50820-SB2-962  
CIVIC 84-87  
ENG. MOUNT, RH



LHC6601

50840-S84-000  
ACCORD '98 4CY  
ENGINE MOUNT



LHC4371

50810-SM4-000  
ACCORD 90-93  
ENG. MOUNT, REAR



LHC0878

50805-SB2-982  
CIVIC 12V '85  
ENG. MOUNT, SIDE



LHC3300

50811-SE0-000  
ACCORD 84-89  
ENGINE MOUNT




LHC3807

50830-SM4-010  
ACCORD '90  
BUFFER



LHC2937

50810-SB2-983  
CIVIC 12V '85  
ENGINE MOUNT, R



LHC4269




50805-SM4-010  
ACCORD '90  
ENGINE MOUNT, RH



LHC4839



50805-S84-A80  
ACCORD '98 AT 4CY  
ENGINE MOUNT, R

# MITSUBISHI Replace parts GALANT, LANCER, ECLIPSE, MIRAGE, PAJERO, L200, L300

|                                                                                                                                                                    |                                                                                                                                                                            |                                                                                                                                                                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <br><b>LHC4419</b><br><b>MB691251</b><br>LANCER MIRAGE '93 1.8<br>ENGINE MOUNT, RH | <br><b>MB691253</b><br>LANCER '93 1.5 AT<br>ENGINE MOUNT, RH                              | <br><b>LHC4049</b><br><b>MB309481</b><br>MITSUBISHI 1.8/2.0<br>ENG. MOUNT, F   |
| <br><b>LHC4288</b><br><b>MB691236</b><br>LANCER, MIRAGE '93 AT<br>ENGINE MOUNT, F  | <br><b>LHC4287</b><br><b>MB691238</b><br>MIRAGE '93 ATM<br>ENGINE MOUNT, R                | <br><b>LHC4050</b><br><b>MB309996</b><br>MITSUBISHI 1.8/2.0<br>ENGINE MOUNT, F |
| <br><b>LHC4285</b><br><b>MB691235</b><br>LANCER, MIRAGE '93 MT<br>ENGINE MOUNT, F  | <br><b>LHC4403</b><br><b>MB691231</b> 1.8<br>LANCER, MIRAGE '93<br>ENGINE MOUNT, LH       | <br><b>LHC3816</b><br><b>MB309799</b><br>MITSUBISHI<br>ENGINE MOUNT, F         |
| <br><b>LHC4590</b><br><b>MB844840</b><br>MIRAGE '93 1.5<br>ENGINE MOUNT, F         | <br><b>LHC4693</b><br><b>MB691230</b> 1.5<br>LANCER, MIRAGE '93<br>ENGINE MOUNT, LH       | <br><b>LHC3821</b><br><b>MB309512</b><br>MIRAGE<br>ENGINE MOUNT, F             |
| <br><b>LHC3594</b><br><b>MB006802</b><br>GALANT, LANCER<br>ENGINE MOUNT, R          | <br><b>LHC4099</b><br><b>MB309261</b><br>LANCER '88 MT<br>ENGINE MOUNT                    | <br><b>LHC4244</b><br><b>MB260670</b><br>PAJERO, L200 '85<br>ENGINE MOUNT, R  |
| <br><b>LHC3729</b><br><b>MB006867</b><br>MITSUBISHI<br>BUFFER                       | <br><b>LHC4299</b><br><b>MB581322</b><br>LANCER '88 ATM<br>ENGINE MOUNT, R                | <br><b>MB436578</b><br>L200 89-92<br>ENGINE MOUNT, F                          |
| <br><b>LHC0951</b><br><b>MB260741</b><br>MITSUBISHI<br>BUFFER                     | <br><b>LHC4882</b><br><b>MB309545</b><br>MIRAGE, TRADIA<br>83-88 MT<br>ENGINE MOUNT, RH | <br><b>LHC4375</b><br><b>MB436365</b><br>L200 87-95<br>ENGINE MOUNT, R      |
| <br><b>MB007188</b><br>COLT 84-90<br>ENGINE MOUNT                                | <br><b>LHC4588</b><br><b>MB309535</b><br>CORDIA G32<br>ENGINE MOUNT                     | <br><b>LHC4352</b><br><b>MB436342</b><br>L300 '88 MT<br>ENGINE MOUNT, R     |
| <br><b>MB436541</b><br>GALANT 89-93 MT<br>ENGINE MOUNT, RH                        | <br><b>LHC4584</b><br><b>MB436041</b><br>STARWAGON 87-89 4G63<br>ENGINE MOUNT, R        | <br><b>LHC0805</b><br><b>MB007038</b><br>L300 80-87<br>ENGINE MOUNT, F      |
| <br><b>LHC4469</b><br><b>MB581029</b><br>MIRAGE '92 ATM<br>TRANS MOUNT, RH        | <br><b>LHC4661</b><br><b>MB309700</b><br>PAJERO '85 MT<br>ENGINE MOUNT, R               | <br><b>LHC2348</b><br><b>MB006809</b><br>L300 80-87<br>ENGINE MOUNT, R      |

# ISUZU Replace parts

## GEMINI, FASTER, LUV, TROOPER, I-MARK, NPR, NKR, DBR, V10

|                                                                                                                                                          |                                                                                                                                                         |                                                                                                                                                           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p>LHC1113<br/>9-53215-802<br/>KB20<br/>ENG. MOUNT, F</p>               |  <p>LHC3652<br/>8-94225-983<br/>LUV UBS13<br/>ENG. MOUNT, RH</p>       |  <p>LHC1133<br/>9-53215-611<br/>TLD<br/>ENGINE MOUNT, RH</p>             |
|  <p>LHC3658<br/>8-94225-549<br/>FASTER<br/>ENG. MOUNT, LH</p>            |  <p>LHC3651<br/>8-94225-984<br/>LUV UBS13<br/>ENG. MOUNT, LH</p>       |  <p>LHC1132<br/>9-53215-612<br/>TLD<br/>ENGINE MOUNT, LH</p>             |
|  <p>LHC3659<br/>8-94225-548<br/>FASTER<br/>ENG. MOUNT, RH</p>            |  <p>LHC3653<br/>8-94243-014<br/>TROOPER UBS52<br/>ENG. MOUNT, LH</p>   |  <p>LHC1114<br/>5-53225-607<br/>KS<br/>ENGINE MOUNT, R</p>              |
|  <p>LHC3660<br/>8-94229-300<br/>FASTER<br/>ENG. MOUNT, R</p>             |  <p>LHC3654<br/>8-94243-013<br/>TROOPER UBS52<br/>ENG. MOUNT, RH</p>   |  <p>LHC4034<br/>8-94172-018<br/>NPR, NKR, NHR<br/>ENGINE MOUNT, RH</p>   |
|  <p>LHC3655<br/>5-93215-002<br/>KB20<br/>ENGINE MOUNT, LH</p>            |  <p>8-94368-598<br/>NPR 4.3<br/>ENGINE MOUNT, RH</p>                   |  <p>LHC4035<br/>8-94172-019<br/>NPR, NKR, NHR<br/>ENGINE MOUNT, LH</p>   |
|  <p>LHC3656<br/>5-93215-003<br/>KB20<br/>ENGINE MOUNT, RH</p>            |  <p>8-94368-599<br/>NPR 4.3<br/>ENGINE MOUNT, LH</p>                   |  <p>LHC1065<br/>1-53215-060<br/>DBR 78-87<br/>ENG. MOUNT, F</p>         |
|  <p>LHC3657<br/>5-93225-289<br/>KB20<br/>ENGINE MOUNT, R</p>            |  <p>8-94150-463<br/>I-MARK 85-89<br/>ENGINE MOUNT, R</p>             |  <p>LHC1066<br/>1-53225-139<br/>DBR 78-87<br/>ENG. MOUNT, R</p>        |
|  <p>LHC4159<br/>8-97066-800<br/>TROOPER 89-96<br/>ENGINE MOUNT, RH</p> |  <p>LHC3820<br/>8-94174-885<br/>I-MARK 85-89<br/>ENGINE MOUNT, F</p> |  <p>LHC1081<br/>1-53215-061<br/>ISUZU CXZ V12F<br/>ENGINE MOUNT, F</p> |
|  <p>LHC4158<br/>8-94422-868<br/>TROOPER 89-96<br/>ENGINE MOUNT, LH</p> |  <p>LHC4165<br/>8-94146-523<br/>I-MARK 85-89<br/>ENGINE MOUNT RH</p> |  <p>LHC1082<br/>1-53225-062<br/>ISUZU V10<br/>ENGINE MOUNT, R</p>     |
|  <p>LHC4157<br/>8-94334-158<br/>ISUZU 92<br/>ENGINE MOUNT, F</p>       |  <p>LHC3971<br/>8-94117-224<br/>I-MARK 85-89<br/>BUFFER</p>          |  <p>LHC3878<br/>1-53215-132<br/>ISUZU EXR<br/>ENG. MOUNT, F</p>        |